

FIBRE GLAST DEVELOPMENTS -- ALL FIBERGLASS REINFORCEMENT -- 5895-00-261-3419

=====
Product Identification
=====

Product ID:ALL FIBERGLASS REINFORCEMENT

MSDS Date:06/04/1986

FSC:5895

NIIN:00-261-3419

Kit Part:Y

MSDS Number: BGXJS

=== Responsible Party ===

Company Name:FIBRE GLAST DEVELOPMENTS

Address:1944 NEVA DRIVE

City:DAYTON

State:OH

ZIP:45414-5525

Info Phone Num:800-821-3283

Emergency Phone Nu

m:513-274-1159

CAGE:1B420

=== Contractor Identification ===

Company Name:FIBRE GLAST DEVELOPMENTS

Address:1944 NEVA DR

Box:City:DAYTON

State:OH

ZIP:45414-5525

Country:US

CAGE:1B420

=====
Composition/Information on Ingredients
=====

Ingred Name:NO INGREDIENT FOR THIS FORMULATION_INGREDIENT

=====
Hazards Identification
=====

LD50 LC50 Mixture:NONE

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO

Reports of Carcinogenicity:NTP:NO IARC

:NO OSHA:NO

Health Hazards Acute and Chronic:HAZARD ASSOCIATED WITH THIS PRODUCT IS
INHALATION OF DUST OR AIRBORNE FIBERS.

Effects of Overexposure:EYE,SKIN:MECHANICAL IRRITATION,ITCHING;
INHALED:RESPIRATORY IRRITATION.

Medical Cond Aggravated by Exposure:NONE

=====
First Aid Measures
=====

First Aid:EYE:FLUSH WITH WATER 15 MIN. SKIN:REMOVE CONTAMINATED
CLOTHING. WASH AREA WITH SOAP AND WATER. LAUNDER CLOTHING BEFORE
REUSE. INHALED:REMOVE FR

OM EXPOSURE. GIVE ARTIFICIAL RESPIRATION OR OXYGEN IF NEEDED. INGESTED:DO NOT INDUCE VOMITING. GIVE WATER OR MILK. (NOTHING BY MOUTH IF UNCONSCIOUS) GET IMMEDIATE MEDICAL CARE. IF SYMPTOMS PERSIST OR ARE SEVERE,GET MEDICAL CARE.

=====
Fire Fighting Measures
=====

Flash Point:NONE

Extinguishing Media:CARBON DIOXIDE,DRY CHEMICAL,FOAM,WATER FOG. USE MEDIA APPROPRIATE FOR SURROUNDING FIRE.

Fire Fighting Procedures:WEAR SELF CONTAINED BREATHING APPARATUS.

Unusual Fire/Explosion Hazard:NONE

=====
Accidental Release Measures
=====

Spill Release Procedures:PICK UP,USING CARE TO MINIMIZE DUST.

Neutralizing Agent:NONE

=====
Handling and Storage
=====

Handling and Storage Precautions:STORE IN A COOL,DRY,WELL VENTILATED AREA.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:USE NIOSH/MSHA APPROVED RESPIRATOR EQUIPPED WITH CARTRIDGE FOR DUST OR SUPPLIED AIR RESPIRATOR IF EXPOSED ABOVE TLV/PEL.

Ventilation:USE NORMAL ROOM VENTILATION.

Protective Gloves:LATEX OR VINYL.

Eye Protection:SAFETY GLASSES.

Work Hygienic Practices:USE GOOD INDUSTRIAL HYGIENE PRACTICE. AVOID CONTACT.

Supplemental Safety and Health

KEY1:N1 PART D OF A KIT CONTAINING 4 PARTS WITH MSDS. KIT SUPPLIED BY ALEK INC. CAGE 65534. KIT IS P/N D-701.

=====
Physical/Chemical Properties
=====

HCC:F2

Appearance and Odor:

GLASS FIBER CLOTH.

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid: YES
NONE
Stability Condition to Avoid: NONE
Hazardous Decomposition Products: NONE

===== Disposal Considerations =====

Waste Disposal Methods: DISPOSE I/A/W FEDERAL, STATE, LOCAL REGULATIONS.
DISCARD AS ORDINARY REFUSE.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.