View NSN Online: https://aerobasegroup.com/nsn/8010-00-515-1568

PRATT AND LAMBERT INC -- LACQUER CAMOUFLAGE DARK GULL GRAY 36231 -- 8010-00-515-1568

Product ID:LACQUER CAMOUFLAGE DARK GULL GRAY 36231

MSDS Date:08/21/1990

FSC:8010

NIIN:00-515-1568

MSDS Number: BHMQH === Responsible Party ===

Company Name: PRATT AND LAMBERT INC

Address:16116 E 13TH ST

Box:2153 City:WICHITA State:KS

ZIP:67201 Country:US

Info Phone Num:316-733-13

61

Emergency Phone Num:716-873-6000 DOT EMER 8002553924

Preparer's Name: W. A. ELLISON

CAGE:61196

=== Contractor Identification ===

Company Name: PRATT AND LAMBERT INC

Box:6027

City:CLEVELAND

State:OH

ZIP:44101-1027 Country:US

Phone:216-566-2902

CAGE:61196

======= Composition/Information on Ingredients ========

Ingred Name: ISOBUTYL ACETATE (SARA III)

CAS:110-19-0

RTECS #:AI4025000 Fraction by Wt: 20%

Other REC Limits:LFL 2.0/UFL 11.0

OSHA PEL:150 PPM

ACGIH TLV:150 PPM; 9192

EPA Rpt

Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name: ISOPROPYL ALCOHOL (SARA III)

CAS:67-63-0

RTECS #:NT8050000 Fraction by Wt: 5%

Other REC Limits:LFL 3.0/UFL 13.0 OSHA PEL:400 PPM/500 STEL ACGIH TLV:400 PPM/500STEL;9192

Ingred Name: NITROCELLULOSE

CAS:9004-70-0

RTECS #:QW0970000 Fraction by Wt: 5%

Other REC Limits: NONE SPECIFIED

Ingred Name:ISOBUTYL ALCOHOL (SARA III)

CAS:78-83-1

RTECS #:NP9625000 Fraction by Wt: 5%

Other REC Limits:LFL 1.0/UFL 11.0

OSHA PEL:100 PPM ACGIH TLV:50 PPM; 9293

EPA Rp

t Qty:5000 LBS

DOT Rpt Qty:5000 LBS

Ingred Name:TITANIUM DIOXIDE

CAS:13463-67-7 RTECS #:XR2275000 Fraction by Wt: 10%

Other REC Limits: NONE SPECIFIED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name:TOLUENE (SARA III)

CAS:108-88-3

RTECS #:XS5250000 Fraction by Wt: 15%

Other REC Limits:LFL 1.7/UFL 7.1 OSHA PEL:200 PPM/150 STEL ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:XYLENES (O-,M-,P- ISOMERS) (SARA III)

CAS:1330-20-7

RTECS #:ZE2100000

Fra

ction by Wt: 5%

Other REC Limits:LFL 1.0/UFL 7.0 OSHA PEL:100 PPM/150 STEL ACGIH TLV:100 PPM/150STEL;9192

EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name: SILICA, CRYSTALLINE - CRISTOBALITE

CAS:14464-46-1 RTECS #:VV7325000 Fraction by Wt: < 5%

Other REC Limits: NONE SPECIFIED

OSHA PEL:SEE TABLE Z3

ACGIH TLV:0.05 MG/M3 RDUST9293

Ingred Name: TALC (CONTAINING NO ASBESTOS)

CAS:14807-96-6

RTECS #:WW2710000 Fraction by Wt: 10%

Other REC Limits: NONE SPECIFIED

OSHA PEL:2 MG/M3 RDUST

ACGIH TLV:2 MG /M3 RDUST; 9192

Ingred Name: SILICA, CRYSTALLINE - QUARTZ

CAS:14808-60-7 RTECS #:VV7330000 Fraction by Wt: < 1%

Other REC Limits: NONE SPECIFIED

OSHA PEL:SEE TABLE Z3

ACGIH TLV:0.1 MG/M3 RDUST;9293

Ingred Name:DI-SEC-OCTYL PHTHALATE (DI-2-ETHYLHEXYL-PHTHALATE) (SARA

III)

CAS:117-81-7

RTECS #:TI0350000 Fraction by Wt: < 1%

Other REC Limits: NONE SPECIFIED

OSHA PEL:5 MG/M3/10 STEL ACGIH TLV:5 MG/M3; 9192

EPA Rpt Qty:100 LBS DOT Rpt Qty:100 LBS

Ingred Name: VOC 5.11 LB/GAL LESS WATER & NEGLIGIBL

Y PHOTOCHEMCALLY REACTIVE MATERIALS 613 G/L LESS WATER RTECS #:9999999VO Other REC Limits:NONE SPECIFIED

============= Hazards Identification ========================

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:NO

Health Hazards Acute and Chronic:SWALLOWING MAY CAUSE GASTROINTESTINAL IRRIT & CHEMICAL PNEUMONITIS. INHALATION MAY CAUSE NOSE/THROAT IRRITATION. EYE & SKIN IRRITANT; HARMFUL AMTS CAN CAUSE SKIN

DEFATTING. OTHER EFFECTS: LUNG DISEASE, PREXISTING RESPIRATORY CONDITIONS, DAMAGE TO LIVER, KIDNEYS, BLOOD, PERMANENT BRAIN & NERVOUS SYSTEM DAMAGE AND DEATH.

Explanation of Carcinogenicity: CRYSTALLINE SILICA AND DI(2-ETHYLHEXYL) PHTHALATE ARE POTENTIAL CARCINOGENS.

Effects of Overexposure:HEADACHES, DIZZINESS, NAUSEA, VOMITING, CONFUSION & SEVERE IRRITATION REACTION IF PRODUCT IS SWALLOWED, INHALED, ABSORBED THROUGH SKIN, OR GETS INTO EYES.

Medical Cond Aggravated by Exposu

re:PREXISTING RESPIRATORY COND MAY BE

AGGRAVATED BY EXPOSURE TO CRYSTALLINE SILICA. REPORTS ASSOCIATED PROLONGED/REPEATED OCCUPATIONAL OVEREXPOSURE TO SOLVENTS W/PERMANENT BRAIN & NERVOUS SYSTEM DAMAGE.

First Aid:SWALLOWING: DO NOT INDUCE VOMITING. CALL POISON CONTROL CENTER IMMED. INHALATION: REMOVE TO FRESH AIR IMMED. IF BREATHING STOPPED, GIVE CPR & KEEP WARM. EYE: FLUSH W/LRG AMTS OF WATER FOR 15 M

IN LIFTI NG UPPER/LOWER LIDS CONTINUOUSLY. SKIN:IMMEDIATELY FLUSH CONTAMINATED AREA W/LRG AMTS OF WATER. REMOVE CONTAMINATED CLOTHES AS WATER IS APPLIED. GET MEDICAL ATTN IMMED FOR ANY OF THESE CONDITIONS.


========== Fire Fighting Measures ================

Flash Point:40F/4C

Lower Limits:SEE INGRED Upper Limits:SEE INGRED

Extinguishing Media:USE CARBON DIOXIDE, FOAM, OR DRY CHEMICAL FOR FLAMMABLE LIQUID FIRES. POLYMER FOAM IS PREFERRED FOR LARGE FIRES.

Fire F



=====

HCC:F2

Boiling Pt:B.P. Text:180 TO 288F

Vapor Density:> THAN AIR

Spec Gravity:1.2

Evaporation Rate & Evaporation R

Percent Volatiles by Volume:71

======== Stability and Reactivity Data ==========

Stability Indicator/Materials to Avoid:YES

STRONG ACIDS OR ALKALINE MATERIALS.

Stability Condition to Avoid:AVOID EXCESSIVE HEAT AND SOURCES OF IGNITION.

Hazardous Decomposition Products:BURNING, HEAT BY WELDING OR CUTTING, WILL PRODUCE SMOKE, CARBON

MONOXIDE, CARBON DIOXIDE, AND OXIDES OF NITROGEN.

Conditions to Avoid Polymerization: KEEP AWAY FROM HEAT SPARKS AND FLAME.

======= Disposal Considerations ===========

Waste Disposal Methods:DISPOSE OF IN I/A/W FEDERAL, STATE & LOCAL LAWS. INCINERATE ONLY IN EPA PERMITTED FACILITY. DO NOT INCINERATE CLOSED CONTAINERS. OBSERVE PRECAUTIONS FOR DISP OF FLAMMABLE MATERIALS. CONTAMINATED ABSOR BENT MAY BE DISPOSED IN A HAZARD WASTE LANDFILL.

Disclaimer (

provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.