Product ID:MARCOLOY #1109;SOFT SOLDER MSDS Date:06/13/1988 FSC:3439 NIIN:01-297-3284 Kit Part:Y MSDS Number: BHXRB === Responsible Party === Company Name:MARCO CO Address: 5722 UNION PACIFIC AVENUE **City:LOS ANGELES** State:CA ZIP:90022-5135 Country:US Info Phone Num:213-723-0711 Emergency Phone Num:213-723-0711 Preparer's Name: BARRY MARDEN CAGE:55278 === Contractor Identification === Company Name:MARCO CO Address:5722 UNION PACIFIC AVENUE Box:City:LOS ANGELES State:CA ZIP:90022-5135 Country:US Phone:213-723-0711 CAGE:55278 Company Name: SPECIALTY TOOLS INC Address:1123 S. HATCHER AVE Box:City:ROWLAND HEIGHTS State:CA ZIP:91748-1003 Country:US Phone:626-912-4467 CAGE:7W874

Ingred Name:TIN CAS:7440-31-5 RTECS #:XP7320000 OSHA PEL: 2 MG/M3 ACGIH TLV:2 MG/M3; 9192

Ingred Name:ZINC (SARA III) CAS:7440-66-6 RTECS #:ZG8600000 OSHA PEL:10 MG ZNO/M3 ACGIH TLV:10 MG ZNO/M3; 9192 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:ACUTE:IRRITATION OF
EYES,SKIN,RESPIRATORY OR G,I.TRACT;REDNESS OR BURNS OF EYES ARE
POSSIBL
E FROM FUMES AND GASES(WELDING PROCESS.)FUMES MAY CAUSE
DIZZINESS,NAUSEA OR DRYNESS.METAL FUMES FEVER DUE TO ZINC OXIDE
FUMES
Explanation of Carcinogenicity:DATA PER MGF MSDS.
Effects of Overexposure:SEE HEALTH HAZARDS DATA.

Medical Cond Aggravated by Exposure:PRE-EXISTING CONDITIONS MAY BE WORSEN.

First Aid:EYES AND SKIN:FLUSH WITH LARGE AMOUNT OF WATER FOR ABOUT 15-20 MINUTES;SEEK MEDICAL ATTENTION IMMEDIAT ELY.INHALATION:REMOVE

TO FRESH AIR;CALL A PHYSICIAN.INGESTION:SEEK MEDICAL ATTENTION IMMEDIATELY.

Extinguishing Media:USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY CHEMICAL IF APPLICABLE.

Fire Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE. Unusual Fire/Explosion Hazard:TOXIC G ASES OR FUMES DUE TO WELDING; FIRE OR EXCESSIVE HEAT MAY CAUSE PRODUCTION OF HAZARDOUS DECOMPOSITION PRODUCTS. Spill Release Procedures: USE PROPER PERSONAL PROTECTION; SWEEP UP OR VACUUM AND COLLECT FOR PROPER DISPOSAL IN AN APPROVED CONTAINER. Handling and Storage Precautions: USE AS DIRECTED Other Precautions: WASH THOROUGHLY AFTER EACH USE. ===== Respiratory Protection: USE NIOSH/MSHA APPROVED RESPIRATOR FOR DUST/MIST/VAPORS IF ABOVE PEL/TLV OR SCBA IN AN ENCLOSED AREA. Ventilation:LOCAL/GENERAL TO MAINTAIN PEL/TLV. Protective Gloves: AS REQUIRED FOR WELDING Eye Protection:SAFETY GLASSES/GOGGLES Other Protective Equipment: PROTECTIVE CLOTHINGS. EYE-WASH FACILITIES, SAFETY SHOWER. Work Hygienic Practices: AVOID CONTACT WITH EYES AND SKIN; DO NOT BREATHE VAPORS/MIST/DUST. WASH THOROUGHLY AFTER EACH USE; DO NOT EAT, DRINK, SMOKE. Supplemental Safety and Health FOLLOW ALL PRECAUTIONS AS APPLICABLE FOR CUTTING AND WELDING .

HCC:N1 Melt/Freeze Pt:M.P/F.P Text:390F,199C Appearance and Odor:SILVER,ODORLESS

Stability Indicator/Materials to Avoid:YES NONE NOTED Stability Condition to Avoid:HIGH TEMPERATURES, SPARKS, AND OPEN FLAMES Hazardous Decomposition Products:TOXIC FUMES OR VAPORS FROM METAL BEING WELDED.(DEPENDS UPON METAL,PROCESS,PROCEDURES AND ELECTRODES BEING USED)

Waste Disposal Methods:CONSULT LOCAL AUTHORITIES;DISPOSAL MUST BE IN ACCORDANCE WITH LOCAL,STATE AND FEDERAL REGULATIONS

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defe

nse. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.