View NSN Online: https://aerobasegroup.com/nsn/9150-01-035-5393

WITCO CHEMICAL CORP **GOLDEN** BEAR OIL CO DIVISION LUBRICATING OIL, GEAR, MULTIPURPOSE -- 9150-01-035-5393

============= Product Identification ========================

Product ID:LUBRICATING OIL, GEAR, MULTIPURPOSE

MSDS Date:02/07/1989

FSC:9150

NIIN:01-035-5393

MSDS Number: BJNYT === Responsible Party ===

Company Name: WITCO CHEMICAL CORP GOLDEN BEAR OIL CO DIVISION

Box:5446 City:OILDALE State:CA

ZIP:93388-5446

Country:US

Info

Phone Num:805-393-7110

Emergency Phone Num:805-393-7110

Preparer's Name: J.T.COOK

CAGE:1F469

=== Contractor Identification ===

Company Name: WITCO CHEMICAL CORP GOLDEN BEAR OIL CO DIVISION

Address: MANOR & NORRIS ROADS

Box:5446 City:OILDALE State:CA

ZIP:93388-5446

Country:US

Phone:805-393-7110/800-424-9300(CHEMTREC)

CAGE:1F469

======= Composition/Information on Ingredients ========

Ingred Name: SOLVENT REFINED HEAVY NAPHTHENIC DISTILLATE, PETROLEUM

CAS:64741-96-4 RTECS #:PY8040000

Ot

her REC Limits: NONE SPECIFIED

Ingred Name:REFINED HEAVY PARAFFINIC DISTILLATES CAS:64741-88-4 Other REC Limits:NONE SPECIFIED OSHA PEL:5 MG/M3 (OIL MIST) ACGIH TLV:5 MG/M3 (OIL MIST)

Ingred Name:OTHER COMPONENTS (TYPE NOT SPECIFIED)

Other REC Limits: NONE SPECIFIED

========= Hazards Identification ================

Routes of Entry: Inhalation:UNKNOWN Skin:YES Ingestion:YES

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:ACUTE:IRRITATIO

N OF

EYES, SKIN, RESPIRATORY OR G.I. TRACTS; REDNESS OR BURNS OF EYES/SKIN POSSIBLE. CHRONIC: DRYING OF SKIN, DEFATTING OR DERMATITIS.

Explanation of Carcinogenicity: DATA PER MSDS

Effects of Overexposure:MAY CAUSE IRRITATION OF EYES,SKIN,RESPIRATORY OR G.I.TRACTS; BURNS OR REDNESS OF EYES/CRACKING OR DRYNESS OF SKIN.

Medical Cond Aggravated by Exposure:PERSONS WITH A HISTORY OF AILMENTS OR WITH A PRE-EXISTING DISEASE INVOLVING THE EYES, SKIN, OR RESPIRATORY TRACT MAY BE AT INCR

EASED RISK FROM EXPOSURE.

First Aid:INHALATION:REMOVE TO FRESH AIR. RESUSCITATE IF NOT BREATHING. GET MEDICAL ATTENTION. EYES:IMMEDIATELY FLUSH WITH PLENTY OF WATER FOR 15 MINUTES HOLDING EYELIDS OPEN. GET MEDICAL ATTENTION. SKIN:REMOVE CONTAMINATED CLOTHING. WASH WITH SOAP AND WATER. IF IRRITATION PERSISTS, GET MEDICAL ADVICE. INGESTION:DO NOT INDUCE VOMITING. GIVE NOTHING BY MOUTH IF UNCONSCIOUS. GET I MMEDIATE

MEDICAL ATTENTION.

Flash Point Method:COC Flash Point:>300F,>149C

Extinguishing Media: USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY CHEMICAL.

Fire Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE.

Unusual Fire/Explosion Hazard:FIRE OR EXCESSIVE HEAT MAY CAUSE PRODUCTION

OF HAZARDOUS DECOMPOSITION PRODUCTS.
========= Accidental Release Measures ==========
Spill Release Procedures:USE PROPER PERSONAL PROTECTION;REMOVE ALL SOURCES OF IGNITION. CONTAIN FREE MATERIAL IF POSSIBLE;USE SUITABLE INERT ABSORBENT MATERIAL AND RECOVER FOR PROPER DISPOSAL IN AN APPROVED CONTAINER. Neutralizing Agent:NOT APPLICABLE.
=========== Handling and Storage =============
Handling and Storage Precautions:STORE IN A COOL, DRY, WEL L VENTILATED AREA. KEEP CONTAINERS TIGHTLY CLOSED WHEN NOT IN USE. PROTECT CONTAINERS FROM PHYSICAL DAMAGE. Other Precautions:DO NOT TAKE INTERNALLY. DO NOT BREATHE MIST. AVOID PROLONGED OR REPEATED BREATHING OF VAPOR. AVOID CONTACT WITH EYES. USE WITH ADEQUATE VENTILATION. WASH THOROUGHLY AFTER HANDLING.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:USE NIOSH/MSHA APPROVED RESPIRATOR AS REQUIRED IF ABOVE PEL/TLV OR SCBA IN AN EN CLOSED AREA. Ventilation:LOCAL/GENERAL TO MAINTAIN PEL/TLV. Protective Gloves:NEOPRENE, NITRILE, OR NATURAL RUBBER Eye Protection:SAFETY GOGGLES WITH OPTIONAL FACE SHIELD Other Protective Equipment:EYE WASH STATION AND SAFETY SHOWER,WORK CLOTHING AND APRON AS REQUIRED. Work Hygienic Practices:OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES. DO NOT WEAR CONTAMINATED CLOTHING OR FOOTWEAR. Supplemental Safety and Health AVOID PROLONGED OR REPEATED EXPOSURE. DO NOT GET ON SKIN OR IN EYES. DO NOT BREATHE VAPORS OR MISTS.
========= Physical/Chemical Properties ==========
HCC:V6 Boiling Pt:B.P. Text:>550F,>288C Vapor Pres: