View NSN Online: https://aerobasegroup.com/nsn/9150-00-965-2400

OCTAGON PROCESS INC. -- MIL-L-26087B AM.I GRADE I LUBRICATING OIL -- 9150-00-965-2400

============= Product Identification ========================

Product ID:MIL-L-26087B AM.I GRADE I LUBRICATING OIL

MSDS Date:05/31/1989

FSC:9150

NIIN:00-965-2400

MSDS Number: BJPFW === Responsible Party ===

Company Name: OCTAGON PROCESS INC.

Address:596 RIVER ROAD

City:EDGEWATER

State:NJ

ZIP:07020-1105 Country:US

Info Phone Num:201-945-940

0

Emergency Phone Num:201-945-9400

CAGE:82925

=== Contractor Identification ===

Company Name: OCTAGON PROCESS INC.

Address:596 RIVER ROAD Box:City:EDGEWATER

State:NJ ZIP:07020 Country:US

Phone:201-945-9400

CAGE:82925

======= Composition/Information on Ingredients ========

Ingred Name: MINERAL OIL (NAPHTHENIC/PARAFFINIC)

Fraction by Wt: >99.0%

OSHA PEL:5MG/CUM,AS OIL MIST ACGIH TLV:5MG/CUM,AS OIL MIST

Ingred Name:OTHER COMPONENTS (TYPE NOT SPECIFIED)

Other REC Limits: NONE SPECIFIED

======= Accidental Rel

ease Measures ==========
Spill Release Procedures:USE PROPER PERSONAL PROTECTION;CONTAIN FREE MATERIAL IF POSSIBLE;USE SUITABLE INERT ABSORBENT MATERIAL AND RECOVER FOR PROPER DISPOSAL IN AN APPROVED CONTAINER. Neutralizing Agent:NOT APPLICABLE.
============ Handling and Storage ==============
Handling and Storage Precautions:STORE IN A COOL, DRY, WELL VENTILATED AREA. KEEP CONTAINERS TIGHTLY CLOSED WHEN NOT IN USE.DO MOT USE CONTAMINATED CLOTHES.
ther Precautions:DO NOT TAKE INTERNALLY. DO NOT BREATHE MIST. AVOID PROLONGED OR REPEATED BREATHING OF VAPOR. AVOID CONTACT WITH EYES. USE WITH ADEQUATE VENTILATION. WASH THOROUGHLY AFTER HANDLING.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:USE NIOSH/MSHA APPROVED RESPIRATOR AS REQUIRED IF ABOVE PEL/TLV OR SCBA IN AN ENCLOSED AREA. Ventilation:LOCAL/GENERAL TO MAINTAIN PEL/TLV. Protective Gloves:NEOPRENE, NITRILE, OR NATURAL RUBBER Ey
e Protection:SAFETY GOGGLES WITH OPTIONAL FACE SHIELD Other Protective Equipment:EYE WASH STATION AND SAFETY SHOWER,WORK CLOTHING AND APRON AS REQUIRED.
Work Hygienic Practices:OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES. DO NOT WEAR CONTAMINATED CLOTHING OR FOOTWEAR.
Supplemental Safety and Health AVOID PROLONGED OR REPEATED EXPOSURE. DO NOT GET ON SKIN OR IN EYES. DO NOT BREATHE VAPORS OR MISTS.

======= Physical/Chemical Properties ======= =======

HCC:V6 Boiling Pt:B.P. Text:610F,321C Vapor Pres:5.0 Spec Gravity:0.93 Evaporation Rate & Deference: