View NSN Online: https://aerobasegroup.com/nsn/3439-01-039-6408

INWELD MFG CORP -- COVERED ELECTRODES FOR MMAW -- 3439-01-039-6408

======== Product Identification ============

Product ID:COVERED ELECTRODES FOR MMAW

MSDS Date:09/01/1989

FSC:3439

NIIN:01-039-6408

MSDS Number: BJRQQ === Responsible Party ===

Company Name: INWELD MFG CORP

Address:1471 JERSEY AVE

Box:6019

City:NEW BRUNSWICK

State:NJ ZIP:08902 Country:US

Info Phone Num:201-545-3800 Emergency Phone Num:201-545

-3800

CAGE:66376

=== Contractor Identification ===

Company Name: INWELD MFG CORP

Address:3962 PORTLAND ST

Box:40

City:COPLAY

State:PA

ZIP:18037-0040

Country:US

Phone:610-261-1900

CAGE:66376

======= Composition/Information on Ingredients ========

Ingred Name:IRON CAS:7439-89-6

RTECS #:NO4565500 Fraction by Wt: 55-70%

Other REC Limits:NONE SPECIFIED OSHA PEL:10 MG/M3(IRON OXIDE) ACGIH TLV:5 MG/M3 (IRON OXIDE)

Ingred Name: MANGANESE (SARA III)

CAS:7439-96-5

RTECS #:OO9275000

Fraction

by Wt: 0.5-2.0% Other REC Limits:NONE SPECIFIED OSHA PEL:(C) 5 MG/M3 DUST ACGIH TLV:5 MG/M3 DUST 9293

Ingred Name: SILICON

CAS:7440-21-3

RTECS #:VW0400000 Fraction by Wt: 0.1-1.0%

Other REC Limits: NONE SPECIFIED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST: 9293

Ingred Name: CHROMIUM (SARA III)

CAS:7440-47-3

RTECS #:GB4200000 Fraction by Wt: 0-3.5%

Other REC Limits: NONE SPECIFIED

OSHA PEL:1 MG/M3

ACGIH TLV:0.5 MG/M3; 9192

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name: MOLYBDENUM

CAS:7439-9

8-7

RTECS #:QA4680000 Fraction by Wt: 0-1.0%

Other REC Limits: NONE SPECIFIED

OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3; 9293

Ingred Name: CALCIUM CARBONATE (MARBLE) (LIMESTONE)

CAS:1317-65-3

RTECS #:EV9580000 Fraction by Wt: 5-12%

Other REC Limits: NONE SPECIFIED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9192

Ingred Name:FLUORSPAR

CAS:14542-23-5 Fraction by Wt: 3-10%

Other REC Limits:NONE SPECIFIED OSHA PEL:2.5 MG/M3 FLUORIDE ACGIH TLV:2.5 MG/M3 FLUORIDE

Ingred Name: POTASSIUM TITANATE

CAS:12030-97-6 Fraction by Wt: 0-2%

Other REC Limits: NONE SPECIFIED

Ingred Name:POTASSIUM ALUMINUM SILICATE (FELDSPAR)

CAS:68476-25-5 Fraction by Wt: 0-2%

Other REC Limits: NONE SPECIFIED

Ingred Name: ALPHA-ALUMINA (ALUMINUM OXIDE) (EPA LISTS ONLY FIBROUS

FORMS) (SARA III)

CAS:1344-28-1

RTECS #:BD1200000 Fraction by Wt: 0-1%

Other REC Limits: NONE SPECIFIED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name: SILICA, AMORPHOUS, DUST

CAS:112945-52-5 RTECS #:VV7310000

Fraction by Wt: 0-2%

Other REC Limits: NONE SPECIFIED

OSHA PEL:6 MG/M3

ACGIH TLV:10 MG/M3; 8990

Ingred Name:TITANIUM DIOXIDE

CAS:13463-67-7 RTECS #:XR2275000 Fraction by Wt: 0-3%

Other REC Limits: NONE SPECIFIED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name:POTASSIUM SILICATE

CAS:1312-76-1 Fraction by Wt: 0-3%

Other REC Limits: NONE SPECIFIED

Ingred Name: SODIUM SILICATE

CAS:1344-09-8 Fraction by Wt: 0-5%

Other REC Limits: NONE SPECIFIED

Ingred Name: CRYOLITE

CAS:15096-52-3

Fraction by

Wt: 0-2%

Other REC Limits: NONE SPECIFIED

Ingred Name:MAGNESITE

CAS:546-93-0

RTECS #:OM2470000 Fraction by Wt: 0-2%

Other REC Limits: NONE SPECIFIED

OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9192

Ingred Name: POTASSIUM HYDROXIDE (SARA III)

CAS:1310-58-3

RTECS #:TT2100000 Fraction by Wt: 0-0.5%

Other REC Limits: NONE SPECIFIED

OSHA PEL:C, 2 MG/M3

ACGIH TLV:C 2 MG/M3; 9192

EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Route

s of Entry: Inhalation:YES Skin:NO Ingestion:NO

Health Hazards Acute and Chronic:FUMES AND GASES CAN BE DANGEROUS TO YOUR HEALTH. ARC RAYS CAN INJURE EYES AND BURN SKIN. ELECTRIC SHOCK CAN KILL. NOISE CAN DAMAGE HEARING.

Explanation of Carcinogenicity: CHROMIUM IS LISTED UNDER NTP AND IARC.

Effects of Overexposure:ACUTE:METALLIC TASTE,NAUSEA,TIGHTNESS OF CHEST,FEVER,DIZZINESS,DRYNESS,IRRITATION OF EYES,NOSE AND THROAT.

ONIC:EXCESSIVE LEVELS MAY CAUSE BRONQUIAL ASTHMA, LUNG FIBROSIS AND PNEUMOCONIOSIS.

Medical Cond Aggravated by Exposure:AGGRAVATION OF EXISTING RESPIRATORY OR ALLERGIC CONDITIONS.HIGHER LEVEL OF LUNG RELATED PROBLEMS AMONG SMOKERS.

First Aid:REMOVE FROM EXPOSURE AND OBTAIN PROMPT MEDICAL ATTENTION. IF NOT BREATHING, GIVE CPR/OXYGEN. EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY AMERICAN RED CROSS.

========

| ====== Fire Fighting Measures ============ |
|--|
| Extinguishing Media:NON-FLAMMABLE. USE EXTINGUISHING MEDIA APPROPIATE FOR SURROUNDING FIRE. Fire Fighting Procedures:WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL FACED SELF CONTAINED BREATHING APPARATUS. COOL FIRE EXPOSED CONTAINERS WITH WATER SPRAY. CONTAIN RUNOFF. Unusual Fire/Explosion Hazard:WELDING ARCS, SPARKS, ETC. MAY IGNITE COMBUSTIBLE MATERIAL. |
| ====== Accidental Release Measures ==================================== |
| Spill Release Procedures:CLEAN UP ANY GRINDING DUST OR WASTE RESIDUE AND PLACE IN APPROPIATE DISPOSAL CONTAINER. |
| ====================================== |
| Handling and Storage Precautions:STORE IN DRY AREA. ELECTRODES EXPOSED TO MOISTURE MAY EXPLODE VIOLENTLY IF USED. DRY MOIST RODS BY BAKING AT 300F FOR TEN HOURS. Other Precautions:TRAIN WELDER TO KEEP HIS HEAD OUT OF THE FUMES.MONITOR AIR TO ENSURE ACCEPTABLE EXPOSURES.AVOID ELECTRICAL SHO |
| CK BY MAINTAINING DRY WORK AREA. WELDING ARC CAN IGNITE COMBUSTIBLES AND FLAMMABLES. |
| ====== Exposure Controls/Personal Protection ======== |
| Respiratory Protection:FUME RESPIRATOR OR AIR SUPPLIED RESPIRATOR IN CONFINED SPACES OR WHERE VENTILATION DOES NOT KEEP EXPOSURE BELOW TLV. |
| Ventilation:LOCAL EXHAUST TO KEEP BELOW TLV. Protective Gloves:WELDER'S GLOVES. Eye Protection:HELMET OR FACE SHIELD WITH FILTER LENS. Other Protective Equipment:SUBSTANTIAL DARK CLOTH,ARM |
| PROTECTOR,APRON,HAT AND SHOULDER PROTECTION. AIR SAMPLING TO DETERMINE CORRECTIVE MEASURES. Work Hygienic Practices:WASH HANDS THOROUGHLY BEFORE EATING,SMOKING OR USING SANITARY FACILITIES. Supplemental Safety and Health NONE. |
| ========= Physical/Chemical Properties ========= |
| HCC:V7 Solubility in Water:INSOLUBLE Appearance and Odor:WELDING ROD. |
| ======== Stability and Reactivity Data ========= |
| Stability Indicator/Materials to Avoid:YES Hazardous D |

| ecomposition Products:FUMES OF IRON,COMPLEX OXIDES OF | |
|---|-------|
| MANGANESE, SILICON, CHROMIUM, MOLYBDENUM, FLUORIDES, CO, CO2, NIT | ROGEN |
| OXIDES,OZONE. | |

======= Disposal Considerations ===========

Waste Disposal Methods:CONSULT WITH YOUR LOCAL ENVIRONMENTAL OFFICER.DISPOSE OF FUMES,FLUX OR WELD GRINDING RESIDUE FROM THE WORK AREA OR FROM FILTERS IN ACCORDANCE WITH FEDERAL,STATE AND LOCAL ENVIRONMENTAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.