

PORTER MFG. & SUPPLY CORP. -- GASGACINCH GASKET SEALER -- 8040-01-125-4673

=====  
Product Identification  
=====

Product ID:GASGACINCH GASKET SEALER

MSDS Date:01/01/1987

FSC:8040

NIIN:01-125-4673

MSDS Number: BJXRY

=== Responsible Party ===

Company Name:PORTER MFG. & SUPPLY CORP.

Address:2215 NO. CHICO AVENUE

City:SOUTH EL MONTE

State:CA

ZIP:91733

Country:US

Info Phone Num:818-448-4578

Emergency P

hone Num:818-448-3243

CAGE:PORTE

=== Contractor Identification ===

Company Name:PORTER MFG. & SUPPLY CORP.

Address:2215 NO. CHICO AVENUE

City:SOUTH EL MONTE

State:CA

ZIP:91733

Country:US

Phone:818-448-3243

CAGE:PORTE

=====  
Composition/Information on Ingredients  
=====

Ingred Name:SOLVENT BLEND (AROMATIC AND ALIPHATIC SOLVENTS)

CAS:64742-86-5

RTECS #:LX3296500

Fraction by Wt: 80%

Other REC Limits:NONE SPECIFIED

OSHA PEL:500 PPM

ACGIH TLV:500 PPM

Ingred Name:ADDITIVES (COMPOUN

DED SYNTHETIC RUBBER, RESINS,  
ANTIOXIDENTS, METAL OXIDES)

Fraction by Wt: 20%

Other REC Limits:NONE SPECIFIED

ACGIH TLV:500 PPM

=====  
===== Hazards Identification =====

Effects of Overexposure:HEADACHE, NAUSEA, LOSS OF APPETITE, BAD TASTE,  
LASSITUDE, IMPAIRMENT OF COORDINATION AND REACTION TIME.

=====  
===== First Aid Measures =====

First Aid:INHALATION: REMOVE TO FRESH AIR AND ADMINISTER ARTIFICIAL  
RESPIRATION, CALL PHYSICIAN IF NECESSARY. SKIN CONTACT: REMOVE WITH  
MINERAL SPIRITS FOLLOWED BY SOAP & WATER. EYE CONTACT: FLOOD WITH  
LARGE QUANTITIES OF WATER FOR TEN MINUTES. INGESTION: DO NOT  
ATTEMPT TO EMPTY STOMACH BY CAUSING VOMITING. CALL PHYSICIAN.

=====  
===== Fire Fighting Measures =====

Flash Point Method:TCC

Flash Point:0F/-18C

Extinguishing Media:CARBON DIOXIDE OR DRY CHEMICAL

Fire Fighting Procedures:TYPICAL OF PAINT, PAINT THINNERS AND GASOLINE.

Unusual Fire/Explosion Hazard:

DANGEROUS WHEN EXPOSED TO OPEN FLAME. CAN  
REACT VIGOROUSLY WHEN EXPOSED TO OXIDIZING MATERIALS.

=====  
===== Accidental Release Measures =====

Spill Release Procedures:PROVIDE ADEQUATE VENTILATION. AVOID BREATHING  
VAPORS. USE RUBBER GLOVES. SOAK UP SPILLAGE WITH CLEAN, DRY RAGS.

=====  
===== Handling and Storage =====

Handling and Storage Precautions:KEEP CONTAINER TIGHTLY CLOSED. STORE  
AS CLOSE AS POSSIBLE TO 70F OUT OF DIRECT SUNLIGHT. KEEP AWAY FROM

HEAT, SPARKS, FLAME AND ELECTRICAL EQUIPMENT.

Other Precautions:AVOID BREATHING OF VAPORS. AVOID PROLONGED REPEATED  
CONTACT WITH SKIN.

=====  
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NOT REQUIRED IF VENTILATION IS ADEQUATE.

Ventilation:LOCAL DILUTION, VENTILATION OF SUFFICIENT VOLUME. KEEP  
VAPOR CONCENTRATES BELOW 500 PPM.

Protective Gloves:66/EQUAL SOLVENT RESISTANT B.F.GOODRICH

Eye Protection:HOLDFAST

& SAFETY GLASSES W/SIDESHIELD

Other Protective Equipment:IF REQUIRED, USE BUREAU OF MINES APPROVED  
TYPE B ORGANIC VAPOR MASK OR BEST RECOMMENDED.

Supplemental Safety and Health

===== Physical/Chemical Properties =====

Vapor Density:2-3

Spec Gravity:0.88

Solubility in Water:NEGLIGIBLE

Appearance and Odor:NEUTRAL/AMBER COLOR. MOBILE LIQUID. PUNGENT SOLVENT  
ODOR.

===== Stability and Reactivity Data =====

Stability Indicator/Materials

to Avoid:YES

AVOID OXIDIZING MATERIALS.

Stability Condition to Avoid:WHEN HEATED IT EMITS TOXIC FUMES.

Hazardous Decomposition Products:OXIDIZING MATERIALS

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH FEDERAL, STATE,  
COUNTY AND LOCAL REGULATIONS. LANDFILL OR INCINERATION. DO NOT  
INCINERATE CONTAINERS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for u

se by elements of the Department

of Defense. The United States of America in no manner whatsoever,

expressly or implied, warrants this information to be accurate and

disclaims all liability for its use. Any person utilizing this

document should seek competent professional advice to verify and

assume responsibility for the suitability of this information to their

particular situation.