View NSN Online: https://aerobasegroup.com/nsn/9150-00-698-2382

CHRYSLER CORPORATION -- MOPAR DEXRON II AUTOMATIC TRANS FLUID 04271243 -9150-00-698-2382

Product ID:MOPAR DEXRON II AUTOMATIC TRANS FLUID 04271243 MSDS Date:04/19/1986 FSC:9150 NIIN:00-698-2382 **MSDS Number: BKHQS** === Responsible Party === Company Name: CHRYSLER CORPORATION Address:6311 LAWRENCE AVE **City:CENTER LINE** State:MI ZIP:48015-9960 Info Phone Num:(313) 9 56-5478 OR 956-5557 Emergency Phone Num: (313) 956-5478 OR 956-5557 CAGE:51926 === Contractor Identification === Company Name: CHRYSLER CORP SERVICE AND PARTS OPERATIONS Address:26311 LAWRENCE AVE Box:City:CENTER LINE State:MI ZIP:48015-9960 Country:US Phone:313-956-5478/313-956-5557 CAGE:86403 Company Name: CHRYSLER CORPORATION Address:26311 LAWRENCE AVE. Box:1718 City:CENTER LINE State:MI ZIP:48015-9960 Phone: (313) 956-5478 OR 956-5557 CAGE:51926

======= Composition/Information on Ingredi

Ingred Name: PARAFFINIC PROCESS OIL

Ingred Name: DISTILLATES (PETROLEUM), SOLVENT-DEWAXED HEAVY PARAFFIN

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:INGESTION: HARMFUL, NAUSEA, VOMITING, DIARRHEA, & ABDOMINAL CRAMPS. EYES: IRRITATION, TEARING. SKIN: IRRITATION, DEFATTING, DRYING. INHALATION: HEADACHE, DIZZINESS, IRRITATION OF UPPER RESPIRATORY TRA CT. Explanation of Carcinogenicity:NONE Effects of Overexposure:INGESTION: HARMFUL. INGESTION: NAUSEA, VOMITING, DIARRHEA, & ABDOMINAL CRAMPS. EYE: IRRITATION & TEARING. SKIN: IRRITATION OF UPPER RESPIRATORY RESPIRATORY. TRACT.

First Aid:INGESTION: INDUCE VOMITING. GIVE LARGE AMOUNTS OF WARM SALT WATER. EYE

: IRRIGATE BY WASHING W/LARGE AMOUNTS OF WATER. SKIN: WASH W/SOAP & WATER. INHALATION: REMOVE TO FRESH AIR AT ONCE. OBTAIN MEDICAL ATTENTION IN ALL CASES.

Flash Point Method:COC Flash Point:370F Extinguishing Media:DRY CHEMICAL, FOAM, CO2, & WATER FOG Fire Fighting Procedures:USE SELF-CONTAINED BREATHING APPARATUS.

Spill Release Procedures: ABSORB W

/CLEAN DRY SAND. ABSORB W/DIATOMACIOUS EARTH. SHOVEL INTO STORAGE CONTAINERS. ELIMINATE ALL IGNITION SOURCES, FLAMES, HOT SURFACES & ELECTRICAL, STATIC OR FRICTIONAL SPARKS. DON'T FLUSH INTO S EWER SYSTEM.

Handling and Storage Precautions: KEEP FROM HEAT, SPARKS, OPEN FLAMES. STORE AT TEMP