H. B. FULLER COMPANY -- FE-0004-A -- 8040-00-998-3339 Product ID:FE-0004-A MSDS Date:12/11/1988 FSC:8040 NIIN:00-998-3339 Kit Part:Y MSDS Number: BKJSZ === Responsible Party === Company Name: H. B. FULLER COMPANY Address:1200 WOLTERS BLVD City: VADNAIS HEIGHTS State:MN ZIP:55110 Country:US Info Phone Num:612-481-3300 Emergency Phone Num:612-481-3300 CAGE:75782 === Contractor Identification === Company Name: H. B. FULLER COMPANY, FOSTER PRODUCTS DIV. CAGE:75782 Company Name: H.B. FULLER COMPANY Address:3500 LEXINGTON AVENUE N. Box:City:ST. PAUL State:MN ZIP:55126-8076 Country:US Phone:612-236-5300/ -5309 FAX CAGE:0DH19 ======= Composition/Information on Ingredients ======== Ingred Name: EPOXY RESIN Fraction by Wt: >10% Other REC Limits: NONE SPECIFIED

Routes of Entry: Inhalation:NO Skin:YES Ingestion:YES

Reports of Carcinogenicity:NTP:NO

PRODUCT MAY CAUSE IRRITATION. SKIN: EPOXY RESINS ARE POTENTIAL DERMAL SENSITIZERS. INHALATION: INHALATION IS NOT A ROUTE OF EXPOSURE.
======================================
First Aid:EYES: FLUSH IMMEDIATELY WITH WATER FOR 15 MINUTES. CONSULT A PHYSICIAN IF IRRITATION PERSISTS. SKIN: WASH AFFECTED AREA WITH SOAP AND WATER. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE.
======================================
Flash Point Method:TCC Flash Point:>200F,>93C Extinguishing Media:USE WATER SPRAY, FOAM, DRY CHEMICAL OR CARBON DIOXIDE. Fire Fighting Procedures:PERSONS EXPOSED TO PRODUCTS OF COMBUSTION SHOULD WEAR SELF-CONTAINED BREATHING APPARATUS AND FULL PROTECTIVE EQUIPMENT.
======== Accidental Release Measures ==========
Spill Release Procedures:WEAR RUBBER GLOVES AND WIPE UP WITH ABSORBENT
MATERIAL. RESIDUE MAY BE REMOVED WITH A CHLORINATED SOLVENT.
======================================
Handling and Storage Precautions:STORE IN A COOL, DRY LOCATION. Other Precautions:AVOID SKIN CONTACT WITH PRODUCT AT ALL TIMES.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:NOT NORMALLY REQUIRED. Ventilation:STANDARD INDUSTRIAL VENTILATION. Protective Gloves:RUBBER GLOVES. Eye Protection:SAFETY GLASSES. Other Protectiv

Health Hazards Acute and Chronic:EYES: DIRECT EYE CONTACT WITH THE

IARC:NO OSHA:NO

e Equipment:PREVENT CONTACT BY USING APPROPRIATE PROTECTIVE CLOTHING.
Work Hygienic Practices:LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. Supplemental Safety and Health
======== Physical/Chemical Properties ==========
Viscosity:25,000 CPS Appearance and Odor:LIQUID
========= Stability and Reactivity Data ==========
Stability Indicator/Materials to Avoid:YES Hazardous Decomposition Products:INCOMPLETE COMBUSTION CAN YIELD LOW MOLECULAR WEIGHT HYDRO CARBONS, CARBON MONOXIDE.
======= Disposal Considerations ===========

Waste Disposal Methods:THIS PRODUCT DOES NOT MEET THE DEFINITION OF HAZARDOUS WASTE. INCINERATE OR DISPOSE OF IN AN APPROVED INDUSTRIAL LANDFILL. CONSULT YOUR STATE OR LOCAL AUTHORITIES IN THE EVENT MORE RESTRICTIVE REQUIRE MENTS APPLY.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense.

The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.