View NSN Online: https://aerobasegroup.com/nsn/8040-01-066-6442

DEXTER CORP, ADHESIVES & STRUCTURAL MATERIALS DIV. -- EPK 0151 PART B - 8040-01-066-6442

============= Product Identification ==================

Product ID:EPK 0151 PART B

MSDS Date:07/11/1989

FSC:8040

NIIN:01-066-6442

Kit Part:Y

MSDS Number: BKJTZ === Responsible Party ===

Company Name: DEXTER CORP, ADHESIVES & STRUCTURAL MATERIALS DIV.

Address: ONE DEXTER DRIVE

City:SEABROOK

State:NH ZIP:03874 Country:US Info Phone

Num:603-474-5541

Emergency Phone Num:603-926-0910 Preparer's Name:DR. SHELDON CLARK

CAGE:1JB33

=== Contractor Identification ===

Company Name: DEXTER CORP THE HYSOL DIV

Address:1 DEXTER DR Box:City:SEABROOK

State:NH ZIP:03874 Country:US

Phone:603-474-5541/FAX: 603-474-5545

CAGE:1JB33

Company Name: THE ROBERT MCKEOWN CO INC

CAGE:ROBER

======= Composition/Information on Ingredients ========

Ingred Name:SILICA, AMORPHOUS (FILLER PARTICLES ARE THOROUGHLY WETTED BY VEHICLE SO AIRBORN

E EXPOSURE DOES NOT OCCUR UNLESS CURED \* CAS:112945-52-5 RTECS #:VV7310000 Other REC Limits: NONE SPECIFIED **OSHA PEL:20 MPPCF** Ingred Name: \*MATERIAL IS SUBSEQUENTLY GROUND, MACHINED OR SANDED. RTECS #:9999999ZZ Other REC Limits: NONE SPECIFIED Ingred Name:TRIETHYLENETETRAMINE CAS:112-24-3 RTECS #:YE6650000 Other REC Limits: NONE SPECIFIED Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: MATERIAL IS CORROSIVE TO SKIN. MAY CAUSE CHEMICAL BURNS TO SKIN AND EYES. REPEAT CONTACT MAY CAUSE SENSITIZATION. Explanation of Carcinogenicity: N/K \*BONDED. FAILURE TO OBSERVE CAUTION MAY RESULT IN EXCESSIVE HEAT BUILD-UP WITH THE RELEASE OF TOXIC GASES. Effects of Overexposure: SKIN RASH, IRRITATION; POSSIBLE BURNS. First Aid:FLUSH SKIN AND EYE CONTACT WITH PLENTY OF WATER. WASH SKIN THOROUGHLY WITH SOAP AND WATER, RUBBING ALCOHOL OR HAND CLEANER. DO NOT USE SOLVENTS. REMOVE SOILED CLOTHING AND WASH BEFORE RE-USE. IF IRRIT ATION PERSISTS, SEE PHYSICIAN. ============ Fire Fighting Measures ========================= Flash Point:265F,129C Extinguishing Media:DRY CHEMICAL OR HALON FIRE EXTINGUISHER, WATER SPRAY, FOAM OR FOG. Fire Fighting Procedures: USE SELF-CONTAINED BREATHING APPARATUS WHEN FIGHTING FIRES IN CONFINED ARE

AS.
Unusual Fire/Explosion Hazard:DENSE SMOKE AND TOXIC GASES MAY BE LIBERATED.
========= Accidental Release Measures ==========
Spill Release Procedures:SCRAPE UP AND TRANSFER TO METAL CONTAINER. WIPE UP REMAINING RESIDUE WITH SOLVENTS, OBSERVING SOLVENT FLAMMABILITY CAUTIONS, OR USE DETERGENT.
========== Handling and Storage ============
Handling and Storage Precautions:KEEP COOL IN ACCORDANCE WITH LABEL INSTRUCTIONS. Other Precauti
ons:FOLLOW RECOMMENDED CURING SCHEDULE.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:NOT REQUIRED WITH GOOD INDUSTRIAL VENTILATION ORGANIC RESPIRATOR. Ventilation:LOCAL EXHAUST RECOMMENDED, MECHANICAL ACCEPTABLE.
Protective Gloves:IMPERVIOUS PLASTIC OR RUBBER.
Eye Protection:SAFETY GLASSES OR GOGGLES. Other Protective Equipment:AS NEEDED TO PROTECT SKIN AND CLOTHING. Supplemental Safety and Health
======================================
Boiling Pt:B.P. Text:531F,277C Vapor Pres:1
Spec Gravity:0.98
Evaporation Rate & Deference: