View NSN Online: https://aerobasegroup.com/nsn/8040-01-184-7171

Product ID:EA 9330.3 PART B MSDS Date:09/29/1989 FSC:8040 NIIN:01-184-7171 Kit Part:Y MSDS Number: BLJNQ === Responsible Party === Company Name: DEXTER ADHESIVES AND STRUCTURAL MATERIALS Address:2850 WILLOW PASS ROAD Box:312 City:PITTSBURG State:CA ZIP:94565 Country:US Info Phone Nu m:415-687-4201 Emergency Phone Num:415-687-4201 OR 800-424-9300 Preparer's Name:SUZANNE FRANZ CAGE:33564 === Contractor Identification === **Company Name: DEXTER CORPORATION ADHESIVE & COATING SYSTEMS** Address:2850 WILLOW PASS ROAD Box:312 **City:BAY POINT** State:CA ZIP:94565-3299 Country:US Phone:202-483-7616 CAGE:33564

Ingred Name: EPOXY RESIN SYSTEM Other REC Limits: NONE SPECIFIED

Ingred Name:SILICA CAS:7631-86-9 Fraction by Wt: < 10% Other REC Limits:NONE SPECIFIED OSHA PEL:20 MPPCF ACGIH TLV:10 MG/M3

Ingred Name:VOC:< 10 G/L ESTIMATED RTECS #:9999999VO Other REC Limits:NONE SPECIFIED

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:MATERIAL MAY BE CORROSIVE TO EYES AND VERY IRRITATING TO SKIN. VAPORS MAY BE IRRITATING. MODERATELY TOXIC BY INGESTIO N. REPEATED CONTACT MAY CAUSE SENSITIZATION.

Effects of Overexposure: POSSIBLE BURNS TO EYES AND SKIN. IRRITATION AND POSSIBLE SENSITIZATION TO SKIN.

First Aid:FLUSH SKIN AND EYE CONTACT WITH PLENTY OF WATER. WASH THOROUGHLY WITH SOAP AND WATER, RUBBING ALCOHOL OR HAND CLEANER. DO NOT USE SOLVENTS. REMOVE SOILED CLOTHING AND WASH BEFORE REUSE. IF IRRITATION PERSISTS, SEE PHYSICIAN.

======= Fire

Flash Point Method:TOC Flash Point:> 300 Extinguishing Media:DRY CHEMICAL OR HALON FIRE EXTINGUISHER, OR WATER SPRAY, FOAM OR FOG.

Fire Fighting Procedures:USE SELF-CONTAINED BREATHING APPARATUS WHEN FIGHTING FIRES IN CONFINED AREAS.

Unusual Fire/Explosion Hazard: DENSE SMOKE AND TOXIC GASES MAY BE LIBERATED.

Spill Release Procedures: WEAR PROTECTIVE CLOTHING, GLOVES AND SAFE

ΤY

GLASSES. SCRAPE UP AND TRANSFER TO METAL CONTAINER. WIPE UP REMAINING RESIDUE WITH SOLVENTS, OBSERVING SOLVENT FLAMMABILITY CAUTIONS.

Handling and Storage Precautions: KEEP COOL IN ACORDANCE WITH LABEL INSTRUCTIONS. STORE AT ROOM TEMPERATURE (77 F) FOR 12 MONTHS. Other Precautions: FOLLOW RECOMENDED CURING SCHEDULE.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection:NO T NEEDED WITH GOOD INDUSTRIAL VENTILATION. Ventilation:LOCAL EXHAUST RECOMMENDED. Protective Gloves:IMPERVIOUS PLASTIC OR RUBBER. Eye Protection:SAFETY GLASSES OR GOGGLES. Other Protective Equipment:AS NEEDED TO PROTECT SKIN AND CLOTHING. Supplemental Safety and Health *TO BE BONDED. FIALURE TO OBSERVE CAUTION MAY RESULT IN EXCESSIVE HEAT

BUILD-UP WITH THE RELEASE OF TOXIC GASES.

Boiling Pt:B.P. Text:435F,224C Vapor Pres: 1 LB TOTAL.DO NOT HEAT MIXED ADHESIVE ABOVE 75F UNLESS CURING SURFACES*

Waste Disposal Methods:DISPOSE OF AS HAZARDOUS WASTE ACCORDING TO FEDERAL, STATE AND LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants thi

s information to be accurate and

disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.