View NSN Online: https://aerobasegroup.com/nsn/8040-00-664-4318

TACC INTERNATIONAL CORP. -- ADHESIVE MA-212 -- 8040-00-664-4318

Product ID: ADHESIVE MA-212 MSDS Date:07/01/1989 FSC:8040 NIIN:00-664-4318 MSDS Number: BLJWJ === Responsible Party === Company Name: TACC INTERNATIONAL CORP. Address: AIR STATION INDUSTRIAL PARK Box:390 City:ROCKLAND State:MA ZIP:02370 Country:US Info Phone Num:617-878-7015 Emergency Phone Num:800-424 -9300 CHEMTREC CAGE:0HZU1 === Contractor Identification === Company Name: TACC INTERNATIONAL CORP Address: AIR STATION INDUSTRIAL PARK Box:City:ROCKLAND State:MA ZIP:02370 Country:US Phone:781-878-7015 CAGE:0HZU1 Ingred Name: HEXANE (N-HEXANE) CAS:110-54-3 RTECS #:MN9275000 Fraction by Wt: 37-58% Other REC Limits:NONE SPECIFIED

OSHA PEL:500 PPM ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name: ACETONE (SARA

III) CAS:67-64-1 RTECS #:AL3150000 Fraction by Wt: 16-25% Other REC Limits:NONE SPECIFIED OSHA PEL:1000PPM ACGIH TLV:750PPM/1000STEL;9293 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:METHYL ETHYL KETONE (2-BUTANONE) (MEK) (SARA III) CAS:78-93-3 RTECS #:EL6475000 Fraction by Wt: 9-15% Other REC Limits:NONE SPECIFIED OSHA PEL:200 PPM/300 STEL ACGIH TLV:200 PPM/300STEL 9192 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:TOLUENE (SARA III) CAS:108-88-3 RTECS #:XS5250000 Fraction by Wt: 2-5% Other REC Limits:NONE SPECIFIED OSHA PEL:200 PPM/150 STEL ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:INHALATION: ACUTE SIGNS OF

OVEREXPOSURE COULD BE HEADACHE, DIZZINESS, NAUSEA, UPPER RESPIRATORY DRYNESS OR IRRITATION, DROWSINESS, MENTAL DEPRES SION OR

NARCOSIS, DIFFICULTY IN BREATHING. CHRONIC EFFEC TS OF OVEREXPOSURE TO SOLVENT VAPORS COULD LEAD TO PERMANENT EFFECTS TO THE NERVOUS SYSTEM, BODY ORGANS OR THE BRAIN. \*

Effects of Overexposure:\*USE WITH ADEQUATE VENTILATION. EYES: IRRITATION. INGESTION: MAY BE HARMFUL OR FATAL IF SWALLOWED. SKIN: REMOVAL OF SKIN OILS, IRRITATION, DERMATITIS, EVEN SENSITIZATION WITH OVEREXPOSURE.

First Aid:INHAL

## ATION: GET FRESH AIR. EYES: FLUSH WITH WATER FOR AT LEAST 15 MINUTES. IF NECESSARY, CALL A PHYSICIAN. SKIN: WASH WITH SOAP AND WATER. INGESTION: CALL POISON CENTER IMMEDIATELY.

Flash Point Method:CC Flash Point:1 Solubility in Water:NIL Appearance and Odor:NEUTRAL, TYPICAL ODOR. Percent Volatiles by Volume:63

Stability Indicator/Materials to Avoid:Y ES STRONG OXIDIZING AGENTS, STRONG ACIDS AND BASES. Stability Condition to Avoid:FIRE, SPARKS, STATIC ELECTRICITY. Hazardous Decomposition Products:CO AND CO2.

Waste Disposal Methods:LIQUID MATERIAL IS DESIGNATED AS HAZARDOUS WASTE UNTIL ALL SOLVENTS AND VAPORS HAVE EVAPORATED. DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS. DRIED ADHESIVE MAY BE DISPOSED OF AS ORDINARY WASTE.

Disclaimer (pro

vided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.