View NSN Online: https://aerobasegroup.com/nsn/9150-00-961-8995

CASTROL INC., BRAY PRODUCTS DIV. -- BRAYCOTE 806 -- 9150-00-961-8995

======== Product Identification ============

Product ID:BRAYCOTE 806 MSDS Date:11/13/1989

FSC:9150

NIIN:00-961-8995

MSDS Number: BMGYF === Responsible Party ===

Company Name: CASTROL INC., BRAY PRODUCTS DIV.

Address:16715 VON KARMAN AVE., SUITE230

City:IRVINE State:CA ZIP:92714 Country:US

Info Phone Num:714-660-9414 Emergency Phone Num:714-66

0-9414

Preparer's Name: KAREL WRIGHT

CAGE:EO288

=== Contractor Identification ===

Company Name: CASTROL INC., BRAY PRODUCTS DIV.

Address:16715 VON KARMAN AVE., SUITE 230

City:IRVINE State:CA ZIP:92714 Country:US

Phone:714-660-9414/ABROAD 202-4837616COLL

CAGE:EO288

Company Name: CASTROL INDUSTRIAL NORTH AMERICA INC SPECIALTY PRODUCTS

DIV

Address:1001 WEST 31ST STREET

Box:City:DOWNERS GROVE

State:IL

ZIP:60515-1280 Country:US


Phone:800-621-2661/ FAX: 630-241-4140

CAGE:2R128

Company Name: CASTROL INDU

STRIAL NORTH AMERICA INC. Address:5511 DISTRICT BLVD Box:City:LOS ANGELES State:CA ZIP:90040 Country:US Phone:213-890-4420 CAGE:98308
======== Composition/Information on Ingredients =========
Ingred Name:"NOT HAZARDOUS" PER MANUFACTURER Fraction by Wt: 100% Other REC Limits:NONE SPECIFIED
======================================
Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Ac ute and Chronic:HEALTH HAZARDS: MAY BE A MILD SKIN IRRITANT TO SOME PEOPLE AFTER PROLONGED EXPOSURE. INHALATION OF DECOMPOSITION PRODUCTS MAY CAUSE RESPIRATOTY IRRITATION AND INDUCE "POLYMER FUME FEVER" CONDITION. Effects of Overexposure:MILD SKIN IRRITATION. INHALE OF DECOMPOSITION PRODUCTS-LUNG IRRITATION, PULMONARY EDEMA "FLU-LIKE SYMPTOMS, EX. FEVER, CHILLS, ETC. Medical Cond Aggravated by Exposure:NONE KNOWN.
======================================
First Aid:EYES-FLUSH WITH PLENTY OF WATER. IF IRRITATION DEVELOPS, SEE DOCTOR. SKIN-WIPE MATERIAL FROM SKIN. WASH WITH SOAP & WATER. REMOVE CONTAMINATED CLOTHING. INGEST-DO NOT INDUCE VOMITING. GIVE 2 GLASSES O F CHARCOAL SLURRY OR WATER. SEE DOCTOR.IF UNCONSCIOUS GIVE NOTHING INHALE-REMOVE FROM EXPOSURE. GIVE OXYGEN IF DEEMED NECESSARY.
======================================

Flash Point:NONE Extinguishing Media:NONE
Fire Fighting Proc



Products:DECOMPOSITION AT HIGH TEMPERATURES >280C YIELDS HYDROGEN FLUORIDE, CARBONYL FLUORIDE AND OTHER ACID FLUORIDES.

====== Disposal Considerations ==========

Waste Disposal Methods:ALL RECOVERED MATERIAL SHOULD BE PACKAGED, LABELED, TRANSPORTED & DISPOSED OF IN ACCORDANCE WITH GOOD ENGINEERING PRACTICES. DISPOSE OF BT METHOD IN COMPLIANCE WITH FEDERAL, STATE AND LOCAL REGULATIO NS REGARDING HEALTH, AIR & WATER POLLUTION.

Disclaimer (pro

vided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.