View NSN Online: https://aerobasegroup.com/nsn/8010-00-756-2411

Product ID:MIL-C-22750D, 30,000 PTA MSDS Date:11/14/1991 FSC:8010 NIIN:00-756-2411 Kit Part:Y MSDS Number: BMQGC === Responsible Party === Company Name:STEELCOTE MANUFACTURING CO Address: ONE STEELCOTE SQUARE City:ST LOUIS State:MO ZIP:63103 Country:US Info Phone Num:314-771-8053 Emergency Phone Num:800-424-9300 CHEMTREC CAGE:93981 === Contractor Identification === Company Name: STEELCOTE MANUFACTURING COMPANY Address: ONE STEELCOTE SQUARE Box:City:ST LOUIS State:MO ZIP:63103-2920 Country:US Phone:314-771-8053 CAGE:93981 Ingred Name:2-PROPANOL (SARA 313) (VAPOR PRESSURE 30.00 MM HG @ 20 C) (LEL 2.00 @ 25 C) CAS:67-63-0 RTECS #:NT8050000 Fraction by Wt: 5 - 10% Other REC Limits:NONE SPECIFIED OSHA PEL:400 PP

M ACGIH TLV:400 PPM/500 PPM STEL

Ingred Name:N-BUTYL ACETATE (VAPOR PRESSURE 10.00 MM HG @ 20 C) (LEL 1.38 @ 38 C) CAS:123-86-4 RTECS #:AF7350000 Fraction by Wt: 5 - 10% Other REC Limits:NONE SPECIFIED OSHA PEL:150 PPM ACGIH TLV:150 PPM/200 PPM STEL EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS Ingred Name:2-ETHOXYETHYL ACETATE (SARA 313) (2.00 MM HG @ 20 C) (LEL 1.70 @ 25 C) CAS:111-15-9 RTECS #:KK8225000 Fraction by Wt: 25 - 30% Other REC Limits: UN CARBIDE 5PPM SKIN OSHA PEL:100 PPM (SKI N) ACGIH TLV:5 PPM (SKIN) Ingred Name: METHYL ETHYL KETONE (SARA 313) (VAPOR PRESSURE 70.20 MM HG @ 20 C) (LEL 1.80 @ 25 C) CAS:78-93-3 RTECS #:EL6475000 Fraction by Wt: 20 - 25% Other REC Limits:NONE SPECIFIED OSHA PEL:200 PPM ACGIH TLV:200 PPM/300 PPM STEL EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS Ingred Name: TOLUENE (SARA III) CAS:108-88-3 RTECS #:XS5250000 Fraction by Wt: 5 - 10% Other REC Limits:NONE SPECIFIED OSHA PEL:200 PPM/150 STEL ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:1000 LBS DOT R

pt Qty:1000 LBS

Ingred Name:XYLENE (SARA 313) (VAPOR PRESSURE 6.60 MM HG @ 20 C) (LEL 1.10 @ 25 C) CAS:1330-20-7 RTECS #:ZE2100000 Fraction by Wt: 1 - 5% Other REC Limits:NONE SPECIFIED OSHA PEL:100 PPM ACGIH TLV:100 PPM/150 PPM STEL EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:SANDING/GRINDING OF DRIED FILM OF PRODUCT MAY BECOME DUST NUISANCE. RTECS #:99999992Z Other REC Limits:*5 MG/M3 RESP DUST OSHA PEL:15 MG/M3 TOTAL DUST* ACGIH TLV:10 MG/M3 TOTAL DUST

Ingred Name:SKIN AB SORPTION MAY CONTRIBUTE TO OVERALL EXPOSURE TO THIS MATERIAL. TAKE APPROPRIATE MEASURE TO PREVENT SKIN CONTACT. RTECS #:99999992Z Other REC Limits:NONE SPECIFIED

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Health Hazards Acute and Chronic:EYE: SEVERE IRRIT, CORNEAL INJURY. SKIN: MOD IRRIT. PROLONG/REPEAT--DEFAT/DRY/DERMATITIS. ABSORPTION-SYMPTMS LIKE INHAL/INGEST. INHAL: IRRIT NOSE, THROAT, RESP T

RACT, MUCOUS MEMBRANES. CENTRAL NERV SY S DEPRESS, PERM BRAIN/NERV SYS DAMAGE. CONC & INHAL-HARM/FATAL. INGEST: MOD TOXIC, KIDNEY DAMAGE, CENTRAL NERV SYS *

Effects of Overexposure:EYE: PAIN, TEAR, RED, SWELL. SKIN: RED/SWELL/RASH. INHAL: RUNNY NOSE/SORE THROAT/COUGH/CHEST DISCOMFORT/SHORT BREATH/REDUCED LUNG FUNCTION. INGEST: SORE THROAT, ABDOM PAIN, NAUSEA, VOMIT, DIARRHEA. CE NT NERV SYS DEPSS: HEADACHE, DIZZY, NAUSEA, INTOX SYMPTMS, UNCONSCIOUS, DEATH. LOSS OF MEM ORY, INTELLECT, COORDINATION. Medical Cond Aggravated by Exposure:PREEXISTING, SKIN, EYE, RESPIRATORY DISORDERS MAY BE AGGRAVATED BY EXPOSURE TO THIS PRODUCT. IMPAIRED REPRODUCTIVE FUNCTION FROM PREEXISTING DISORDERS MAY BE AGGRAVATED BY EXPOSURE TO THIS PRODUCT.

First Aid:EYE: IMMED FLUSH EYES W/WATER 15 MIN EYELIDS OPEN. GET IMMED MED AID. SKIN: REMOVE CONTAM CLOTHING & SHOES. WIPE EXCESS FROM SKIN & FLU

SH W/WATER & SOAP. GET MED ATTN IF IRRIT OCCURS. INGEST: DON'T IN DUCE VOMITING UNLESS DR DIRECTS. IF VOMIT21FEB92URS, KEEP HEAD BELOW HIPS (PREVENT ASPIRATION INTO LUNGS). CONSULT DR, HOSP, POISON CNTRL CTR/TRANSPORT TO EMERGENCY FACILITY.

Flash Point Method:TCC
Flash Point:20.0F,-6.7C
Extinguishing Media:USE WATER FOG, FOAM, DRY CHEMICAL OR CARBON DIOXIDE.
Fire Fighting Procedures:FLAMM. EVACUATE UNPROTECTED
. DON'T ENTER
CONFINED FIRE SPACE W/O HELMET, FACE SHIELD, BUNKER COAT, GLOVES, RUBBER BOOTS & POSSITIVE PRESSURE NIOSH-APPRVD SCBA.
Unusual Fire/Explosion Hazard:COOL CNTNRS EXPOS TO HEAT W/WATER TO PREVENT VAPOR PRESSURE BLDUP (STOP CNTNR RUPTURE). COOL CNTNR AREAS EXPOS TO FLAME W/WATER (STOP CNTNR STRUCTURE WEAKENING)

Spill Release Procedures:LRG: EVACUATE UNPROTECTED. WEAR RSPRTR/PROTECTIVE CLOTHING. S TOP LEAK IF NO RISK. USE WATER FOG TO SUPPRESS IF VAPOR CLOUD FORMS. REMOVE W/VACUUM TRUCK/PUMP TO STOR/SALV TANK. USE ABSORB ON RESIDUE. P LACE IN NON-LEAKING CNTNR. FLUSH AREA W/WATER TO** Neutralizing Agent:N/K **REMOVE TRACE RESIDUE. SEAL TIGHTLY FOR PROPER DISPOSAL.

Handling and Storage Precautions: KEEP LIQ/VAPOR FROM HEAT/IGNIT SOURCES. HOT SURFACES MAY IGNITE PRODUCT. VAPORS MAY ACCUMULATE/TR AVEL TO IGNITION SOURCES DISTANT FROM HANDLING SITE. Other Precautions: KEEP CNTNRS CLOSED WHEN NOT IN USE. USE W/ADEQUATE VENT. CNTNRS, EVEN IF EMPTY, CAN CONTAIN EXPLOSIVE VAPORS/HAZARDOUS PRODUCT RESIDUES.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection: IF EXPOSURE EXCEEDS THE PEL/TLV, USE THE APPROPRIATE NIOSH APPROVED RESPIRATOR.

Ventilation: USE VENT AS REQUIRED TO CONTROL VAPOR CONCENTRATIONS--AT LEAST 10 AIR CHANGES PER HR RECOMM

FOR GOOD GENERAL ROOM VENT.

Protective Gloves:WEAR APPROP GLOVES--PREVENT SKIN CONTACT

Eye Protection: SAFETY GLASSES, GOGGLES, SPLASH SHIELD

Other Protective Equipment:WEAR APPROPRIATE PROTECTIVE CLOTHING TO PREVENT CONTACT WITH SKIN AND CLOTHING.

Work Hygienic Practices:WASH W/SOAP & WATER BEFORE EATING, DRINKING, SMOKING OR USING TOILET. EYE WASH STATIONS/SAFETY SHOWERS SHOULD BE AVAIL.

Supplemental Safety and Health

*DEPRESSION. ASPIRATION OF MAT'L INTO LUNGS MAY RESULT IN SEVERE LUNG

DAMAGE. MAT'L IS PRESUMED TO BE FETOTOXIC, CAUSE INJURY TO BONE MARROW/BLOOD CELLS, BIRTH DEFECTS, INCREASED FETAL LETHALITY, DELA YED FETAL DEVELOPMENT. CHRONIC OVEREXPOS MAY CAUSE INJURY TO KIDNEY & LIVER, INJURY TO TESTES.

Vapor Density:>1 Evaporation Rate & amp; Reference: