View NSN Online: https://aerobasegroup.com/nsn/3439-01-323-9369

ALL-STATE WELDING PRODUCTS, INC. -- BARE ALUMINUM WELDING WIRE -- 3439-01-323-9369

Product ID:BARE ALUMINUM WELDING WIRE MSDS Date:02/12/1988 FSC:3439 NIIN:01-323-9369 MSDS Number: BMQQG === Responsible Party === Company Name: ALL-STATE WELDING PRODUCTS, INC. Address:5112 ALLENDALE LANE Box:600 **City:TANEYTOWN** State:MD ZIP:21787 Country:US Info Phone Num:800-638-1 647 OR 310-756-4330 Emergency Phone Num:800-638-1647 CAGE:69482 === Contractor Identification === Company Name: ALL-STATE PRODUCTS/ DIV OF ESAB GROUP, INC Address:5112 ALLENDALE ST Box:600 **City:TANEYTOWN** State:MD ZIP:21787 Country:US Phone:1-410-756-4330 CAGE:69482

Ingred Name:SILICON CAS:7440-21-3 RTECS #:VW0400000 Other REC Limits:NONE SPECIFIED OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name:IRON CAS:7439 -89-6 RTECS #:NO4565500 Other REC Limits:NONE SPECIFIED OSHA PEL:5 MG/M3 ACGIH TLV:10 MG/M3 AS FE2O3

Ingred Name:COPPER (SARA III) CAS:7440-50-8 RTECS #:GL5325000 Other REC Limits:NONE SPECIFIED OSHA PEL:0.1MG/M3 FUME/1 DUST ACGIH TLV:0.2MG/M3 FUME; 9192 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:MANGANESE (SARA III) CAS:7439-96-5 RTECS #:OO9275000 Other REC Limits:NONE SPECIFIED OSHA PEL:(C) 5 MG/M3 DUST ACGIH TLV:5 MG/M3 DUST 9293

Ingred Name:MAGNESIUM CAS:7439-95-4 RTECS #:OM2 100000 Other REC Limits:NONE SPECIFIED

Ingred Name:CHROMIUM (SARA III) CAS:7440-47-3 RTECS #:GB4200000 Other REC Limits:NONE SPECIFIED OSHA PEL:1 MG/M3 ACGIH TLV:0.5 MG/M3; 9192 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:ZINC OXIDE CAS:1314-13-2 RTECS #:ZH4810000 Other REC Limits:NONE SPECIFIED OSHA PEL:15MG/M3 TDUST/5 FUME ACGIH TLV:10MG/M3 TDUST; 9293

Ingred Name:TITANIUM, METAL CAS:7440-32-6 RTECS #:XR1700000 Other REC Limits:NONE SPECIFIED

Ingred Name:COBALT (SARA III) CAS:7440-48-4 RTECS #:GF8750000 Other REC Limits:NONE SPECIFIED OSHA PEL:0.1 MG/M3;AS CO ACGIH TLV:0.05 MG/M3;DUST 9293

Ingred Name:ALUMINUM (SARA III) CAS:7429-90-5 RTECS #:BD0330000 Other REC Limits:NONE SPECIFIED OSHA PEL:15MG/M3 DUST/5 FUME ACGIH TLV:10MG/M3 DUST; 9192

LD50 LC50 Mixture:UNCLASSIFIED WELDING FUMES=5MG/M3 PEL Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:YES IARC:YES OSHA: NO

- Health Hazards Acute and Chronic:ACUTE-OVEREXPOSURE TO WELDING FUMES MAY RESULT IN DISCOMFORT. CHRONIC-OVEREXPOSURE MAY LEAD TO S'DEROSIS (IRON DEPOSITS IN THE LUNG) AND IS BELIEVED BY SOME TO AFFECT PULMONARY FUNCTIONS.
- Explanation of Carcinogenicity:CHROMIUM HAS BEEN IDENTIFIED BY IARC AND/OR NTP AS POTENTIAL CANCER CAUSING AGENTS.
- Effects of Overexposure:FUMES AND GASES CAN BE DANGEROUS TO YOUR HEALTH. EXPOSURE TO WELDING FUMES MAY CAUSE DIZZINESS, NAUSEA OR DRYNESS
- OR IRRITATION OF NISE, THROAT OR EYES. ARC RAYS CAN INJURE EYES AND BURN SKIN. ELECTRI C SHOCK CAN KILL.
- Medical Cond Aggravated by Exposure:AGGRAVATION OF PRE-EXISTING RESPIRATORY OR ALLERGIC CONDITIONS MAY OCCUR IN SOME WORKERS.

First Aid:CALL FOR MEDICAL AID. EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY THE AMERICAN RED CROSS.

Flash Point:NON

FLAMMABLE Extinguishing Media:NONE SPECIFIED BY MANUFACTURER. Fire Fighting Procedures:NONE SPECIFIED BY MANUFACTURER. Unusual Fire/Explosion Hazard:WELDING ARC AND SPARKS CAN IGNITE COMBUSTIBLES.

Other Precautions: WHEN ELECTRODES AND FLUXES ARE CONSUMED, THE FUME AND GAS DECOMPOSITION PRODUCTS GENERATED ARE DIFFERENT IN FORM FROM THE INGREDIENTS LISTED. NEW COMPOUNDS NOT IN THE ELECTRODES MAY FORM.

Exposure Controls/Personal Protection ========

Respiratory Protection:USE RESPIRABLE FUME RESPIRATOR OR AIR SUPPLIED RESPIRATOR WHEN WELDING IN CONFINED SPACES WHERE LOCAL EXHAUST OR VENTILATION DOES NOT KEEP EXPOSURE BELOW TLV.

Ventilation: USE LOCAL AND GENERAL VENTILATION TO KEEP AIRBORNE

CONCENTRATIONS OF DUST OR FUMES BELOW THE TLV DURING USE.

Protective Gloves:WELDERS LEATHER GLOVES

Eye Protection:FLASH GOGGLES/FACE SHIELD W/LENS

Other Protective Equipment:WEAR HEAD, HAN

D & BODY PROTECTION TO PREVENT

INJURY FROM RADIATION, SPARKS & SHOCK. (ARM PROTECTORS, APRONS, HATS, ETC)

Work Hygienic Practices: WASH THOROUGHLY BEFORE EATING OR SMOKING. LAUNDER CONTAMINATIED CLOTHING BEFORE REUSE.

Supplemental Safety and Health

WELDING AND HOT CUTTING FUMES & GASES CANNOT BE CLASSIFIED SIMPLY. THEIR COMPOSITION AND QUANTITY ARE DEPENDENT ON THE METAL BEING WELDED, THE PROCEDURES, PROCESSES AND THE TYPE OF WIRE OR ELECTRODES USED. OTHER INFLUENCING FACT ORS ARE THEPRESENCE OF

CONTAMINANTS.

HCC:N1

Stability Indicator/Materials to Avoid:YES NONE SPECIFIED BY MANUFACTURER. Stability Condition to Avoid:NONE SPECIFIED BY MANUFACTURER. Hazardous Decomposition Products:COMPLEX OXIDES OF IRON, CHROMIUM, COPPER, MANGANESE, SILICONE. GASES OF CARBON MONOXIDE & DIOXIDE, OZONE, NITROGEN OXIDE

============

Waste Disposal Methods:PREVENT WASTE FROM CONTAMINATING SURROUNDING ENVIRONMENT. DISCARD ANY PRODUCT, RESIDUE, DISPOSABLE CONTAINER, OR LINER IN AN ENVIRONMENTALLY ACCEPTABLE MANNER IN FULL COMPLIANCE WITH FEDERAL, STATE & LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever,

expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.