View NSN Online: https://aerobasegroup.com/nsn/8030-00-051-4011

FLAMEMASTER CORP THE CHEM SEAL DIV -- CS 2725, PART B -- 8030-00-051-4011

========= Product Identification ==============

Product ID:CS 2725, PART B

MSDS Date:08/16/1991

FSC:8030

NIIN:00-051-4011

Kit Part:Y

MSDS Number: BNSWP === Responsible Party ===

Company Name: FLAMEMASTER CORP THE CHEM SEAL DIV

Address:11120 SHERMAN WAY

City:SUN VALLEY

State:CA ZIP:91352 Country:US

Info Phone Num:818-982-1650

Emergency Ph

one Num:800-424-9300 CHEMTREC Preparer's Name:HERBERT H MOORE

CAGE:14439

=== Contractor Identification ===

Company Name: FLAMEMASTER CORP THE CHEM SEAL DIV

Address:11120 SHERMAN WAY

Box: City: SUN VALLEY

State:CA

ZIP:91352-4949 Country:US

Phone:818-982-1650

CAGE:14439

======= Composition/Information on Ingredients ========

Ingred Name:TRIETHYLENE PENTAMINE

CAS:68822-50-4 RTECS #:TQ0525000 Fraction by Wt: 5%

Other REC Limits:5 PPM

Ingred Name: VOC: 1 GM/LITER

RTECS #:9999999VO

Other R

========= Hazards Identification ===========
Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:VAPOR/MIST CAN IRRITATE THE NOSE & THROAT. SEVERELY IRRITATING TO EYES AND SKIN. MATERIAL CAN CAUSE SKIN SENSITIZATION AND DERMATITIS. Effects of Overexposure:HEADACHE, DIZZINESS, TEARING OF EYES AND NOSE IRRITATION. ITCHING OF SKIN WITH SIGN OF RED NESS.
Medical Cond Aggravated by Exposure:ASTHMA, LIVER.
======================================
First Aid:EYE ANC SKIN CONTACT: FLUSH EYES WITH WATER FOR AT LEAST 15 MINUTES. CONSULT PHYSICIAN, WASH SKIN WITH SOAP AND WATER.
======================================
Flash Point Method:TCC Flash Point:>200F,>93C Extinguishing Media:FOAM, CO2, DRY CHEMICAL, WATER SPRAY. Fire Fighting Procedures:IN CONFINED AREAS WEAR SELF-CONTAINED
BREATHING APPARATUS. Unusual Fire/Explosion Hazard:OXIDES OF NITROGEN, MAY BE PRODUCTS OF COMBUSTION.
======== Accidental Release Measures ==========
Spill Release Procedures:SCOOP UP AND RETURN TO CONTAINER. WASH AREA WITH SOAP AND WATER.
========== Handling and Storage ============
Handling and Storage Precautions: AVOID CONTACT WITH SKIN, EYES AND CLOTHING. WASH CONTAMINATED CLOTHING BEFORE REUSE.

EC Limits:NONE SPECIFIED

Other Precautions:STORE IN COOL, DR

HCC:N1
Boiling Pt:B.P. Text:550F,288C
Melt/Freeze Pt:M.P/F.P Text:LIQ@RM TEMP
Vapor Pres: