

BUCKEYE RUBBER PRODUCTS INC -- HOSE, NONMETALLIC, ZZ-H-428 TY-1, GRB, CL-2 --
4720-00-288-9743

===== Product Identification =====

Product ID: HOSE, NONMETALLIC, ZZ-H-428 TY-1, GRB, CL-2

MSDS Date: 01/01/1987

FSC: 4720

NIIN: 00-288-9743

MSDS Number: BNWKL

=== Responsible Party ===

Company Name: BUCKEYE RUBBER PRODUCTS INC

Address: 637 N JACKSON ST

Box: 389

City: LIMA

State: OH

ZIP: 45802-0389

Country: US

Info Phone

Num: 419-228-4441 / FAX 419-222-5010

Emergency Phone Num: 419-228-4441

CAGE: 94519

=== Contractor Identification ===

Company Name: BUCKEYE RUBBER PRODUCTS INC

Address: 637 N JACKSON ST

Box: 389

City: LIMA

State: OH

ZIP: 45802-0389

Country: US

Phone: 419-228-4441

CAGE: 94519

===== Composition/Information on Ingredients =====

Ingred Name: "NOT HAZARDOUS"

Fraction by Wt: 100%

Other REC Limits: NONE RECOMMENDED

===== Hazards Identification =====

Routes of Entr

y: Inhalation:YES Skin:NO Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:ACUTE- SMOKE DURING BURNING MAY CAUSE IRRITATION OF EYES, RESPIRATORY TRACT AND SKIN. CHRONIC- NONE KNOWN.
Effects of Overexposure:SMOKE DURING BURNING MAY CAUSE IRRITATION OF EYES, RESPIRATORY TRACT AND SKIN.
Medical Cond Aggravated by Exposure:NONE KNOWN.

=====
===== First Aid Measures =====

First Aid:GET MEDICAL ATTENTION
IF SYMPTOMS PERSIST. SKIN:WASH WITH SOAP & WATER. EYE:FLUSH WITH WATER FOR 15 MINUTES, HOLDING EYELIDS OPEN. INHALED:REMOVE TO FRESH AIR & PROVIDE OXYGEN/CPR IF NEEDED. ORAL:NOT LIKELY.

=====
===== Fire Fighting Measures =====

Extinguishing Media:WATER, ABC DRY CHEMICAL, PROTEIN TYPE AIR FOAM. USE WATER SPRAY TO COOL FIRE EXPOSED CONTAINERS.
Fire Fighting Procedures:WEAR NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS.
Unusual Fire/Explosion Hazard:NONE KNOWN.

=====
===== Handling and Storage =====

Handling and Storage Precautions:STORAGE- STORE IN A COOL, DRY VENTILATED AREA.
Other Precautions:WASH THOROUGHLY AFTER HANDLING.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NIOSH-APPROVED DUST RESPIRATOR IF REQUIRED TO MAINTAIN EXPOSURES DURING CUTTING BELOW SAFE EXPOSURE LIMITS.
Ventilation:REQUIRED DURING CUTTING.
Protective Gloves:RECOMMENDED
Eye Protection:DESIRABLE DURING CUTTING
Other Protective Equipment:EYE BATH STATION
Work Hygienic Practices:WASH EXPOSED SKIN SURFACES PRIOR TO EATING, DRINKING OR SMOKING TO MINIMIZE EXPOSURE.
Supplemental Safety and Health

=====
===== Physical/Chemical Properties =====

HCC:N1
Solubility in Water:INSOLUBLE
Appearance and Odor:HOSE

=====
===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES
NONE KNOWN.
Stability Condition

to Avoid:FIRE, EXCESSIVE HEAT, FLAME

Hazardous Decomposition Products:CARBON MONOXIDE, CARBON DIOXIDE AND
SMALL AMOUNT OF OXIDES OF NITROGEN, AROMATIC AND ALIPHATIC
HYDROCARBONS

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH ALL LOCAL, STATE
AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department

of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.