View NSN Online: https://aerobasegroup.com/nsn/8030-00-515-2271

Product ID:WS-516A ACCELERATOR

MSDS Date:01/01/1987

FSC:8030

NIIN:00-515-2271

Kit Part:Y

MSDS Number: BPFXX === Responsible Party ===

Company Name: J & R INDUSTRIES INC. Address: 800 EAST ANAHEIM STREET

City:WILMINGTON

State:CA ZIP:90744 Country:US

Info Phone Num:213-830-9904 Emergency Phone Num:213-

830-9904 CAGE:DO380

=== Contractor Identification ===

Company Name: J & R INDUSTRIES, INC Address: 800 EAST ANAHEIM STREET

City:WILMINGTON

State:CA ZIP:90744

Phone:310-476-7121

CAGE:DO380

Company Name: J AND R INDUSTRIES (FACTORY LOCATION)

Address:800 E. ANAHEIM ST

Box:City:WILMINGTON

State:CA ZIP:90744 Country:US

Phone:310-476-7121

CAGE:7X230

====== Composition/Information on Ingredients ========

Ingred Name:LEAD DIOXIDE

CAS:1309-60-0

RTECS #:OG0700000 Fraction by Wt: 70%

Other RE

Ingred Name:PLASTICIZER TERPHENYL Fraction by Wt: 26% Other REC Limits:NONE SPECIFIED
Ingred Name:ZINC STEARATE CAS:557-05-1 RTECS #:ZH5200000 Fraction by Wt: 2% Other REC Limits:NONE SPECIFIED OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3 TDUST; 9293
Ingred Name:STEARIC ACID CAS:57-11-4 RTECS #:WI2800000 Fraction by Wt: 2% Other REC Limits:NONE SPECIFIED
======================================
First Aid:WASH WITH PLENTY OF SOAP AND WATER.
======================================
Flash Point:400F,204C Extinguishing Media:STANDARD COMMERCIAL EXTINGUISHER Fire Fighting Procedures:STANDARD Unusual Fire/Explosion Hazard:NONE
======== Accidental Release Measures =========
Spill Release Procedures:WASH WITH PLENTY OF WATER.
=========== Handling and Storage ============
Handling and Storage Precautions:CONTAINS TOXIC LEAD COMPOUND. AVOID CONTACT WITH SKIN AND INGESTION. ALWAYS WASH HANDS BEFORE EATING & SMOKING. Other Precautions:IF ACCELERATOR CONTACTS SKIN FLUSH AREA WITH WARM WATER. IN CASE OF INGESTION OBTAIN MEDICAL ATTENTION. STORE IN CLOSED CONTAINERS AWAY FROM HEAT OR FLAME.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:USE ADEQUATE VENTILATION. Protective Gloves:USE PROTECTIVE GLOVES Eye Protection:USE GOGGLES Supplemental Safety and Health ===================================

Spec Gravity:1.5 Evaporation Rate & Description Rat
Solubility in Water:NONE
Appearance and Odor:BROWN PASTE Percent Volatiles by Volume:NIL
T Growth Volatiles by Volatile. IVIE
========= Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES Stability Condition to Avoid:AVOID CONTACT WITH SKIN. CONTAINS LEAD.
======= Disposal Considerations ==========
Waste Disposal Methods:SAME PROCEDURES AS FOR TOXIC LEAD PRODUCTS.
Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and

assume responsibility for the suitability of this information to their

perties ========

HCC:F4

particular situati

on.