

DARCO SOUTHERN INC -- BUNA-N A NITRILE SHEET -- 5330-00-618-9623
===== Product Identification =====

Product ID:BUNA-N A NITRILE SHEET
MSDS Date:11/30/1988
FSC:5330
NIIN:00-618-9623
MSDS Number: BPJDQ
=== Responsible Party ===
Company Name:DARCO SOUTHERN INC
Address:253 DARCO DRIVE
Box:454
City:INDEPENDENCE
State:VA
ZIP:24348
Country:US
Info Phone Num:703-773-2711
Emergency Phone Num:703-773-2711
CAGE:3N264

=== Contractor Identification ===
Company Name:DARCO SOUTHERN INC
Address:253 DARCO DRIVE
Box:454
City:INDEPENDENCE
State:VA
ZIP:24348
Country:US
Phone:703-773-2711
CAGE:3N264

===== Composition/Information on Ingredients =====

Ingred Name:THERE ARE NO HAZARDOUS MATERIALS IN THIS PRODUCT.
RTECS #:9999999ZZ
Other REC Limits:NONE RECOMMENDED

===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO
Re

ports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:WHEN THERMALLY DECOMPOSED MAY CAUSE
POLYMER FUMED FEVER AND FLU-LIKE SYMPTOMS.
Effects of Overexposure:FLU LIKE SYSTEMS.

=====
First Aid Measures
=====

First Aid:MOVE TO FRESH AIR - REFER TO A PHYSICIAN.

=====
Fire Fighting Measures
=====

Flash Point Method:OC
Flash Point:300F,149C
Extinguishing Media:NONE SPECIFIED BY MANUFACTURER.
F
Fire Fighting Procedures:RECOMMEND USE OF SELF-CONTAINED BREATHING
APPARATUS, PROTECTIVE CLOTHING AND GOGGLES.
Unusual Fire/Explosion Hazard:BLACK SMOKE MAY CAUSE TEARING.

=====
Accidental Release Measures
=====

Spill Release Procedures:AVOID CONTACT WITH SKIN - WASH WITH SOAP AND
WATER.

=====
Handling and Storage
=====

Handling and Storage Precautions:TEMPERATURES ABOVE 500F REQUIRES FACE
MASK WITH AIR SUPPLY. DO NOT
SMOKE OR CONTAMINATE.
Other Precautions:NONE

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:ADEQUATE VENTILATION IS SUFFICIENT.
Ventilation:ADEQUATE VENTILATION.
Protective Gloves:YES
Eye Protection:ALWAYS A GOOD IDEA.
Other Protective Equipment:NONE SPECIFIED BY MANUFACTURER.
Work Hygienic Practices:NONE SPECIFIED BY MANUFACTURER.
Supplemental Safety and Health
NONE

=====
Physical/Chemical Properties
=====

HCC:N1
Spec G

ravity:1.32

Solubility in Water:NEGLIGIBLE

Appearance and Odor:BLACK RUBBER - MILD ODOR.

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

ABOVE 250C: HYDROFLUORIC ACID GAS, PERFLUOROCARBON OLEFINS.

Stability Condition to Avoid:TEMPERATURES ABOVE 500F WITHOUT ADEQUATE VENTILATION SHOULD BE AVOIDED.

Hazardous Decomposition Products:NONE SPECIFIED BY MANUFACTURER.

===== Disposal Considerations =====

Waste Disposal Methods:LANDFILL IN ACCORDANCE WITH LOCAL, STATE, AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and

assume responsibility for the suitability of this information to their particular situation.