View NSN Online: https://aerobasegroup.com/nsn/2530-01-158-1458

COOPER INDUSTRIES INC WAGNER BRAKE DIV -- MX728AR -- 2530-01-158-1458

Product ID:MX728AR MSDS Date:01/06/1993

FSC:2530

NIIN:01-158-1458

Kit Part:Y

MSDS Number: BPVRG === Responsible Party ===

Company Name: COOPER INDUSTRIES INC WAGNER BRAKE DIV

Address:3700 FOREST PARK BLVD

City:ST LOUIS

State:MO ZIP:63018 Country:US

Info Phone Num:314-537-8700

Emergency Phone Nu m:314-537-8700

Preparer's Name: HMIS TECHNICIAN

CAGE:01957

=== Contractor Identification ===

Company Name: COOPER INDUSTRIES INC

Address:16500 SOUTH MAIN

Box:419

City:MISSOURI CITY

State:TX ZIP:77459 Country:US

Phone:713-499-8511

CAGE:01957

Company Name: FEDERAL MOGUL CORP / SUB WAGNER BRAKE

Address:6565 WELLS AVE

Box:7224

City:SAINT LOUIS

State:MO ZIP:63177 Country:US

Phone:800-323-5473

CAGE:63477

======= Composition/Information on Ingredients ========

Ingred Name: DUST, NUISANCE

Othe

======================================
Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:NONHAZARDOUS. MECHANICS MAY FIND SOME NUISANCE DUST WHEN SERVICING VEHICLES WITH THIS PRODUCT. THIS DUST MAY CAUSE SOME MINOR RESPIRATORY IRRITATION. Explanation of Carcinogenicity:NONE Effects of Overexposure:INHALATION: COUGHING, WHEEZING, SHORTNESS OF BREATH. Medical Cond Aggravated by Exposure:NONE
======================================
First Aid:INHALED: REMOVE PERSON TO FRESH AIR. EYES: FLUSH WITH WATER FOR 15 MINUTES. SEE DOCTOR. SKIN: WASH WITH SOAP AND WATER. INGESTED: CALL DOCTOR.
======================================
Extinguishing Media:MEDIA APPROPRIATE FOR SURROUNDING FIRE. Fire Fighting Procedures:WEAR SELF-CONTAINED BREATHING APPARATUS AND PROTECTI VE CLOTHING. Unusual Fire/Explosion Hazard:NONE
========= Accidental Release Measures ==========
Spill Release Procedures:SWEEP UP AND PLACE IN CONTAINER FOR DISPOSAL. Neutralizing Agent:NONE
=========== Handling and Storage ============
Handling and Storage Precautions:KEEP DRY. WET BRAKE SURFACES PRIOR TO SERVICING TO CONTROL DUST. Other Precautions:NONE
====== Exposure Controls/Personal Protection ========
Respiratory Protection

r REC Limits:NONE RECOMMENDED