

QCM COMPANY -- P7002 PLASTISOL -- 8030-01-332-3771

=====  
Product Identification  
=====

Product ID:P7002 PLASTISOL

MSDS Date:10/22/1991

FSC:8030

NIIN:01-332-3771

MSDS Number: BQYPD

=== Responsible Party ===

Company Name:QCM COMPANY

Address:930 SO. CENTRAL AVE.

City:KENT

State:WA

ZIP:98032

Country:US

Info Phone Num:206-859-0933

Emergency Phone Num:800-424-9300

Preparer's Name:ROY WHEELDON

CAGE:8L872

=== Contractor Identification ===

Company Name:Q C M CO

Address:930 CENTRAL AVE S

Box:City:KENT

State:WA

ZIP:98032-6105

Country:US

Phone:253-859-0933, FAX 253-859-0935

CAGE:8L872

=====  
Composition/Information on Ingredients  
=====

Ingred Name:VINYL CHLORIDE MONOMER

CAS:75-01-4

RTECS #:KU9625000

Fraction by Wt: 350F,>177C

Extinguishing Media:DRY CHEMICAL, REGULAR FOAM OR WATER FOG.

Fire Fighting Procedures:WEAR SELF-CONTAINED BREATHING APPARATUS IF  
IGNITED.

Unusual Fire/Ex

losion Hazard:TOXIC GASES CAN FORM - CARBON DIOXIDE,  
CARBON MONOXIDE, VARIOUS HYDROCARBONS.

===== Accidental Release Measures =====

Spill Release Procedures:SMALL: ABSORB ON VERMICULITE OR FLOOR DRY.  
LARGE: PUMP TO SALVAGE TANK.

===== Handling and Storage =====

Handling and Storage Precautions:CONTAINERS MAY BE HAZARDOUS WHEN  
EMPTIED DUE TO VAPOR BUILD-UP. STORE BETWEEN 50F AND 90F, AWAY FROM  
HEAT OR FLAME.

Other

Precautions:ALL HAZARD PRECAUTIONS IN THE DATA SHEET MUST BE  
OBSERVED.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:RECOMMENDED IF LOCAL EXHAUST. NIOSH APPROVED.  
Ventilation:LOCAL EXHAUST: RECOMMENDED FOR HEAT PROCESSING. SPECIAL:  
MECAHNICAL (GENERAL) RECOMMENDED.  
Protective Gloves:POLYETHYLENE TYPE.  
Eye Protection:SAFETY GLASSES.  
Other Protective Equipment:WASH WITH SOAP AND WATER IF CONTACT WITH  
SKIN. WASH CONTAMINATED CLOTHING BEFOR  
E RE-USE.

Supplemental Safety and Health

===== Physical/Chemical Properties =====

Spec Gravity:(H2O=1) 1.1  
Solubility in Water:NEGLIGIBLE  
Appearance and Odor:VARIOUS COLORED LIQUID - VISCOUS.

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES  
STRONG OXIDIZING AGENTS.  
Stability Condition to Avoid:HIGH TEMPERATURES.  
Hazardous Decomposition Products:CARBON MONOXIDE, CARBON DIOXIDE,  
VARIOUS HYDROCARBONS,

# HYDROGEN CHLORIDE.

## ===== Disposal Considerations =====

Waste Disposal Methods:INCINERATE ACCORDING TO LOCAL AND FEDERAL STANDARDS.

Disclaimer (provided with this information by the compiling agencies):  
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.