View NSN Online: https://aerobasegroup.com/nsn/3439-01-127-6944

Product ID:718 MSDS Date:05/08/1989 FSC:3439 NIIN:01-127-6944 **MSDS Number: BRJKY** === Responsible Party === Company Name: UNIVERSAL WIRE WORKS INC Address:7111 LONG DR **City:HOUSTON** State:TX ZIP:77087 Country:US Info Phone Num:713-649-3828 Emergency Phone Num:215-371-2000 CAGE:0BCE4 === Contractor Identification = == Company Name: IDENTECHS COMPANY, DIV OF AXXIOM AEROSPACE Address:3183 RED HILL Box:City:COSTA MESA State:CA ZIP:92626 Country:US Phone:714-250-1290 CAGE:0BLE4 Company Name: UNIVERSAL WIRE WORKS INC. Address:7111 LONG DRIVE Box:City:HOUSTON State:TX ZIP:77087 Country:US Phone:713-649-3828 CAGE:0BCE4

Ingred Name:NICKEL (SARA III) CAS:7440-02-0 RTECS #:QR5950000 Fraction by Wt: 52% Other REC Limits:NONE RECOMMENDED OSHA PEL:1 MG/M3 ACGIH TLV:1 MG/M3; 9293

Ingred Name:IRON OXIDE CAS:1309-37-1 RTECS #:NO7400000 Fraction by Wt: 18% Other REC Limits:NONE RECOMMENDED OSHA PEL:10 MG/M3 (FE) ACGIH TLV:5 MG/M3(FE),B2; 9293

Ingred Name:CHROMIUM (SARA III) CAS:7440-47-3 RTECS #:GB4200000 Fraction by Wt: 18.4% Other REC Limits:NONE RECOMMENDED OSHA PEL:1 MG/M3 ACGIH TLV:0.5 MG/M3; 9293 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:COLUMBIUM CAS:7440-03-1 Fraction by Wt: 5.2% Other REC Limits:NONE RECOMMENDED

Ingred Name:MO LYBDENUM CAS:7439-98-7 RTECS #:QA4680000 Fraction by Wt: 3.1% Other REC Limits:NONE RECOMMENDED OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3; 9293

Ingred Name:COBALT (SARA III) CAS:7440-48-4 RTECS #:GF8750000 Fraction by Wt: 1% Other REC Limits:NONE RECOMMENDED OSHA PEL:0.1 MG/M3;AS CO ACGIH TLV:0.05 MG/M3;DUST 9293

Ingred Name:TITANIUM DIOXIDE CAS:13463-67-7 RTECS #:XR2275000 Fraction by Wt: 1% Other REC Limits:NONE RECOMMENDED OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Nam

e:COPPER (SARA III) CAS:7440-50-8 RTECS #:GL5325000 Fraction by Wt: 0.3% Other REC Limits:NONE RECOMMENDED OSHA PEL:0.1MG/M3 FUME/1 DUST ACGIH TLV:0.2MG/M3 FUME; 9293 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:MANGANESE (SARA III) CAS:7439-96-5 RTECS #:OO9275000 Fraction by Wt: 0.1% Other REC Limits:NONE RECOMMENDED OSHA PEL:(C) 5 MG/M3 DUST ACGIH TLV:5 MG/M3 DUST 9293

Routes of Entry: Inhalation:YES Skin:NO I ngestion:NO Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:NO Health Hazards Acute and Chronic:ACUTE: INHALATION OF WELDING FUMES MAY CAUSE NERVOUS SYSTEM AND MUSCLE IRREGULARITIES, IRRITATION OF EYES, NOSE, THROAT, AND RESPIRATORY SYSTEM, METAL FUME FEVER. CHRONIC: INHALATION OF FUMES MAY CAUS E CANCER AND AFFECT LUNG FUNCTION. Explanation of Carcinogenicity:CONTAINS NICKEL AND CHROMIUM WHICH ARE LISTED BY BOTH IARC AND NTP. Effects of Overexposure:INHALATION: NAUSEA, DIZ ZINESS, DRYNESS OF NOSE AND THROAT, COUGHING, WHEEZING AND SHORTNESS OF BREATH. EYES: REDNESS, TEARING, BLURRED VISION.

Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

First Aid:INHALATION: REMOVE TO FRESH AIR. RESUSCITATE IF NEEDED. EYES: FLUSH WITH PLENTY OF WATER FOR 15 MINUTES. SEE DOCTOR. SKIN: WASH WITH SOAP AND WATER. INGESTION: DO NOT INDUCE VOMITING. SEE DOCTOR.

Extinguishing Media:USE MEDIA APPROPRIATE FOR SURROUNDING FIRE. Fire Fighting Procedures:WEAR SELF-CONTAINED BREATHING APPARATUS AND FULL PROTECTIVE GEAR.

Unusual Fire/Explosion Hazard:NON-FLAMMABLE; BUT SPARKS AND WELDING ARC MAY IGNITE COMBUSTIBLES DURING USE.

Spill Release Procedures: PICK UP RODS. SWEEP UP OR MOP. PLACE RESIDUE IN A CONTAINER FOR DISPOSAL.

Neut

ralizing Agent:NONE SPECIFIED BY MANUFACTURER.

Handling and Storage Precautions:REMOVE ANY COMBUSTIBLES FROM WORK AREA: SPARKS OR WELDING ARC COULD IGNITE NEARBY COMBUSTIBLES. Other Precautions:NONE SPECIFIED BY MANUFACTURER.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection:USE NIOSH/MSHA APPROVED RESPIRATOR FOR WELDING FUMES OR SUPPLIED AIR RESPIRATOR IN CONFINED SPACES OR W HERE FUME

CONCENTRATION EXCEEDS REGULATORY LIMITS.

Ventilation: USE MECHANICAL OR LOCAL EXHAUST OR BOTH TO MAINTAIN LEVELS OF FUMES BELOW REGULATORY LIMITS.

Protective Gloves:WELDERS WORK GLOVES

Eye Protection: WELDERS HELMET WITH CORRECT LENSES

Other Protective Equipment: CLOTHING TO PROTECT ENTIRE BODY FROM SPARKS.

Work Hygienic Practices: WASH HANDS AFTER USE AND BEFORE EATING,

DRINKING, OR SMOKING. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. Supplemental Safety and Health

=========

HCC:N1

Boiling Pt:B.P. Text:HIGH Melt/Freeze Pt:M.P/F.P Text:>2400F,>131 Vapor Pres:NIL Vapor Density:NIL Spec Gravity:7.5-8.5 Solubility in Water:INSOLUBLE Appearance and Odor:SOLID, ODORLESS METAL

Stability Indicator/Materials to Avoid:YES NONE SPECIFIED BY MANUFACTURER. Stability Condition to Avoid:NONE SPECIFIED BY MANUFACTURER. Hazardous Decomposition Products:ME

TAL FUMES

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any per son utilizing this

document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.