

FLAMEMASTER CORP THE CHEM SEAL DIVISION -- CS 3204, PART B -- 8030-00-850-0759

=====  
Product Identification  
=====

Product ID:CS 3204, PART B

MSDS Date:06/15/1990

FSC:8030

NIIN:00-850-0759

MSDS Number: BRKHV

=== Responsible Party ===

Company Name:FLAMEMASTER CORP THE CHEM SEAL DIVISION

Address:11120 SHERMAN WAY

City:SUN VALLEY

State:CA

ZIP:91352

Country:US

Info Phone Num:818-982-1650

Emergency Pho

ne Num:800-424-9300 CHEMTREC

Preparer's Name:HERBERT MOORE

CAGE:14439

=== Contractor Identification ===

Company Name:FLAMEMASTER CORP THE CHEM SEAL DIV

Address:11120 SHERMAN WAY

Box:City:SUN VALLEY

State:CA

ZIP:91352-4949

Country:US

Phone:818-982-1650

CAGE:14439

=====  
Composition/Information on Ingredients  
=====

Ingred Name:MANGANESE DIOXIDE (DUST) (EXPOSURE LIMITS BASED ON DUST  
PARTICLES. THAT DO NOT EXIST IF WETTED OUT)

CAS:1313-13-9

RTECS #:OP0350000

Fraction by Wt: 65

%

Other REC Limits:NONE SPECIFIED

OSHA PEL:5 MG/M3

ACGIH TLV:5 MG/M3

Ingred Name:VOC: 1 GRAM/LITER

RTECS #:9999999VO

Other REC Limits:NONE SPECIFIED

=====  
Hazards Identification  
=====

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:IMPAIRMENT OF CENTRAL NERVOUS SYSTEM.

Effects of Overexposure:SLUGGISHNESS, SLEEPLESSNESS AND/OR WEAKNESS IN  
THE LEGS, WHEN EXCESSIVE

INHALATION EXPOSURE TO DUST OCCURS.

TARGET ORGANS: CENTRAL NERVOUS SYSTEM, BLOOD,  
KIDNEYS.

Medical Cond Aggravated by Exposure:NONE KNOWN

=====  
First Aid Measures  
=====

First Aid:EYES: FLUSH WITH LARGE AMOUNTS OF WATER, CONTACT PHYSICIAN.  
SKIN: WASH WITH SOAP AND WATER.

=====  
Fire Fighting Measures  
=====

Flash Point:NOT FLAMMABLE

Extinguishing Media:DRY CHEMICAL, CO2, FOAM WATER

Fire Fighting Procedure

res:IN CONFINED AREAS WEAR SELF-CONTAINED  
BREATHING APPARATUS.

Unusual Fire/Explosion Hazard:EXPLOSION HAZARD IF HEATED WITH  
OXIDIZABLE MATERIALS.

=====  
Accidental Release Measures  
=====

Spill Release Procedures:SCOOP UP AND TRANSFER TO SAFETY CONTAINER,  
WASH SURFACE WITH SOAP AND WATER.

=====  
Handling and Storage  
=====

Handling and Storage Precautions:STORE IN A COOL, DRY AREA. WASH HANDS  
BEFORE EATING, DRINKING  
OR SMOKING AFTER HANDLING THIS PRODUCT.

=====  
Exposure Controls/Personal Protection  
=====

Respiratory Protection:NONE NEEDED

Protective Gloves:RUBBER

Eye Protection:SAFETY GLASSES

Other Protective Equipment:APPROPRIATE TO PREVENT PROLONGED CONTACT  
WITH SKIN.

Work Hygienic Practices:TRAIN PERSONNEL IN SAFE HANDLING OF THIS  
PRODUCT.

Supplemental Safety and Health

=====  
Physical/Chemical Properties  
=====

Melt/Freeze Pt:M.P/F.P Text:LIQ@RM TE

MP  
Spec Gravity:2.0 (WATER=1)  
pH:9.0  
Viscosity:1000 POISES  
Evaporation Rate & Reference:NIL  
Solubility in Water:NEGLIGIBLE  
Appearance and Odor:BLACK PASTE, OILY ODOR  
Percent Volatiles by Volume:2.0

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES  
REDUCING AGENTS AND COMBUSTIBLE, H2S, POTASSIUM AZIDE  
Stability Condition to Avoid:NONE  
Hazardous Decomposition Products:CO2, CO, NO, NO2, DUST

===== Disposal Considerations =====

Waste Disposal Methods:REACT WITH BASE COMPONENT AND DISPOSE AS SOLID WASTE ACCORDING TO FEDERAL, STATE AND LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):  
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.