View NSN Online: https://aerobasegroup.com/nsn/8010-01-309-0327

Product ID:MIL-P-53022B, TYPE II CATALYST, PART B MSDS Date:12/02/1993 FSC:8010 NIIN:01-309-0327 Kit Part:Y **MSDS Number: BTGLN** === Responsible Party === Company Name: HENTZEN COATINGS, INC Address:6937 W MILL ROAD City:MILWAUKEE State:WI ZIP:53218 Country:US Info Phone Num:414-353 -4200 Emergency Phone Num:414-353-4200/800-424-9300 CHEMTREC Preparer's Name: JANE FREEMAN CAGE:09225 === Contractor Identification === **Company Name: HENTZEN COATINGS INC** Address:6937 WEST MILL ROAD Box:18749 City:MILWAUKEE State:WI ZIP:53218 Country:US Phone:414-353-4200 CAGE:09225

Ingred Name:1-METHOXY-2-PROPANOL SOLVENT CAS:107-98-2 RTECS #:UB7700000 Fraction by Wt: 45.016% Other REC Limits:NONE RECOMME OSHA PEL:100 PPM;STEL 150 PPM ACGIH TLV:100 PPM;STEL 150 PPM

Ingred Name:EPOXY RESIN Fraction by Wt: 30-40% Other REC Limits:NONE RECOMME

Ingred Name:METHYL ISOBUTYL KETONE (SARA III) CAS:108-10-1 RTECS #:SA9275000 Fraction by Wt: 2.333% Other REC Limits:NONE RECOMME OSHA PEL:50 PPM; STEL 75 PPM ACGIH TLV:50 PPM; STEL 75 PPM EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:1,2,4-TRIMETHYLBENZENE SOLVENT (SARA III) CAS:95-63-6 RTECS #:DC3325000 Fraction by Wt: 4.468% Other REC Limits:NONE RECOMME OSHA PEL:25 PPM ACGIH TLV:25 PPM

Ingred Name:AROMATIC HYDROCARBON SOLVENT (MIXTURE OF C8'S TO C10'S) CAS:64742-95-6 Fraction by Wt: 8.797%

Ingred Name:VOC: 4.991 LBS/GAL; 598.071 GRAMS/LITER RTECS #:9999999VO Other REC Limits:NONE RECOMME

Health Hazards Acute and Chronic:INHALATION: ANESTHETIC. RESPIRATORY TRACT IRRITATION, ACUTE NERVOUS SYSTEM DEPRESSION (HEADACHE, DIZZINESS, STAGGERING, CONFUSION, COMA). SKIN OR EYE: IRRITAT ION.

CHRONIC OVEREXPOSURE: REPEATED OR PRO LONGED OVEREXPOSURE WITH PERMANENT BRAIN & NERVOUS SYSTEM DAMAGE, LIVER, KIDNEY DAMAGE. Medical Cond Aggravated by Exposure:ASTHMA AND OTHER RESPIRATORY AILMENTS; CHEMICAL SENSITIZATION.

First Aid:INHALATION: REMOVE FROM EXPOSURE. RESTORE BREATHING. KEEP WARM AND QUIET. NOTIFY PHYSICIAN. EYES: FLUSH IMMEDIATELY WITH LARGE AMOUNTS OF RUNNING WATER FOR AT LEAST 15 M INUTES. TAKE TO A PHYSICIAN FOR MEDICAL TREATMENT. SKIN: WASH AFFECTEDAREAS WITH SOAP AND WATER. REMOVE CONTAMINATED CLOTHING. CONSULT A PHYSICIAN. INGESTION: CALL A PHYSICIAN OR POISON CONTROL CENTER IMMEDIATELY.

Flash Point Method:TCC Flash Point:60.0F,15.6C Lower Limits:0.9 Upper Limits:36.5 Extinguishing Media:FOAM, DRY CHEMICAL, CO2 Fire Fighting Procedures:WEAR PROTECT EQUIP INCLUDING SCBA. WATER MAY BE INEFFECTIVE, USE WATER (FOG NOZZLES PREFERRED) COOL CLOSED CNTNR TO PREVENT PRESSURE BLDUP,AUTOIGNITN,EXPLOSION. Unusual Fire/Explosion Hazard:KEEP CONTAINER TIGHTLY CLOSED. KEEP FROM HEAT/IGNIT SOURCE. CLOSED CNTNR MAY EXPLODE W/HEAT. DON'T APPLY TO HOT SRFCS. NEVER USE WELD/CUT TORCH ON/NEAR DRUM.

Spill Release Procedures:REMOVE ALL SOURCES OF IGNITION (FLAMES, HOT SURFACES, ELECTRICAL, STATIC OR FRICTIONAL SPARKS). AVOID BREATHING

VAPORS. VENTILATE AREA. CONTAIN & REMOVE WITH INERT ABSORBENT AND NONSPARKING TOOLS.

Handling and Storage Precautions:DON'T STORE ABOVE 120F. STORE LARGE QUANTITIES IN BUILDINGS DESIGNED TO COMPLY WITH OSHA 1910.106. KEEP AWAY FROM SPARKS AND OPEN FLAME. DON'T INGEST.
Other Precautions:GROUND CONTAINERS WHEN POURING. AVOID LIQUID FREE FALL >FEW INCHES. USE W/VENT & RESP EQUIP. AVOID
PROLONGED VAPOR BREATHING. AVOID PROLONGED/REPEATED SKIN CONTACT. EMPTIED CNTNR RETAIN HZD RESIDUE/EX PLOSIVE VAPOR. OBEY ALL HZD PRECAUTIONS.

====== Exposure Controls/Personal Protection ==========

Respiratory Protection:WHEN SPRAYED IN OUTDOOR OR DURING SANDING/GRINDING: NIOSH MECHAN FILTER RESPRTR (RMV SOLID PARTICLES). RESTRICTED AREA: NIOSH CHEM/MECHAN FILTER. CONFINED AREA: NIOSH AIR SUPPLIED RSPRTR/HOOD. USE NIO SH RSPRTR WHEN CUT/WELD HAZING TORCH. Ventilation:GENRL DILUTN/LOCAL EXHAUST VENT TO KEEP BELOW PEL/TLV WHILE MIXING,APPLICATION,CURING,REMOVE DECOMP FROM WELD/FLAME CUT. Protective Gloves:REQ'D FOR PROLONGED OR REPEATED CONTACT Eye Protection:SAFETY EYEWEAR W/SPLASH GUARDS/SIDE SHLD Other Protective Equipment:USE PROTECTIVE SKIN CREAM WHERE CONTACT IS LIKELY. PREVENT PROLONGED SKIN CONTACT WITH CONTAMINATED CLOTHING. Work Hygienic Practices:WASH CONTAMINATED CLOTHING BEFORE REUSE. WASH HANDS BEFORE EATING OR SMOKING. SM OKE IN DESIGNATED AREAS ONLY. Supplemental Safety and Health

Boiling Pt:B.P. Text:232 TO 418F Decomp Temp:Decomp Text:400F,204C Vapor Pres:15.00 @68F Vapor Density:> AIR Spec Gravity:0.97 Viscosity:20-40"ZAHNCUP Evaporation Rate & amp; Reference:FASTER THAN BUTYL ACETATE Solubility in Water:NEGLIGIBLE Appearance and Odor:AMBER LIQUID, SOLVENT ODOR Percent Volatiles by Volume:66.41

Stability Indicator/Materials to Avoid:YES STRONG OXIDIZERS Hazardous Decomposition Products:MAY PRODUCE HAZARDOUS FUMES WHEN HEATED TO DECOMPOSITION AS IN WELDING. MAY CONTAIN CARBON MONOXIDE & CARBON DIOXIDE.

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE ABOVE 120F. STORE LARGE QUANTITIES IN BUILDINGS DESIGNED TO COMPLY WITH OSHA 1910.106. KEEP AWAY FROM SPARKS AND
OPEN FLAME. EPA HAZARDOUS WASTE NUMBER/CODE: D001, IGNITABLE. DISPOSAL METHODS: INCINERATION.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any pers

on utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.