View NSN Online: https://aerobasegroup.com/nsn/8030-00-145-0156

QCM COMPANY -- A-1104 PRIMER FOR PLASTISOL COATINGS -- 8030-00-145-0156

Product ID:A-1104 PRIMER FOR PLASTISOL COATINGS MSDS Date:05/20/1994 FSC:8030 NIIN:00-145-0156 Kit Part:Y MSDS Number: BTVWQ === Responsible Party === Company Name: QCM COMPANY Address:930 SOUTH CENTRAL AVENUE City:KENT State:WA ZIP:98032 Country:US Info Phone Num:206-859-0933 **Emergency Phone** Num:206-859-0933/800-424-9300 CHEMTREC Preparer's Name: ROY WHEELDON CAGE:8L872 === Contractor Identification === Company Name: Q C M CO Address:930 CENTRAL AVE S Box:City:KENT State:WA ZIP:98032-6105 Country:US Phone: 253-859-0933, FAX 253-859-0935 CAGE:8L872

Ingred Name:METHYL ETHYL KETONE (SARA III) (SEC 304: FINAL RQ 5000 LBS) CAS:78-93-3 RTECS #:EL6475000 Fraction by Wt: 61.8% Other REC Limits:NONE RECOMMENDED OSHA PEL:200 PPM ACGIH TLV:200 PPM EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:ETHANOL (SEC 304: FINAL RQ 100 LBS) CAS:64-17-5 RTECS #:KQ6300000 Fraction by Wt: 20% Other REC Limits:NONE RECOMMENDED OSHA PEL:1000 PPM ACGIH TLV:1000 PPM

Ingred Name:VOC PER LITER: 5.78 LBS/GAL (692 GRAMS/LITER); VOC PER LITER MINUS EXEMPT SOLVENTS & WATER: 5.78 LBS/GAL RTECS #:9999999VO Other REC Limits:NONE RECOMMENDED

Routes of Entry: Inh alation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:SKIN, EYE, RESPIRATORY AND GASTROINTESTINAL IRRITATION, POSSIBLY SEVERE. EXCESSIVE INHALATION MAY PRODUCE CENTRAL NERVOUS SYSTEM DEPRESSION. Explanation of Carcinogenicity:NONE KNOWN

First Aid:EYE CONTACT: IMMEDIATELY FLUSH WITH LARGE AMOUNTS OF WATER FOR AT LEAST 15 MINUTES. SEEK MEDICAL ATTE NTION. SKIN CONTACT: REMOVE CONTAMINATED CLOTHING. WASH THOROUGHLY WITH SOAP AND WATER. INHALATION: SEEK IMMEDIATE MEDICAL ATTENTION. DO NOT INDUCE VOMITING.

Flash Point Method:TCC Flash Point:16.0F,-8.9C Lower Limits:1.8 Upper Limits:19.0 Extinguishing Media:CARBON DIOXIDE, DRY CHEMICAL Fire Fighting Procedures:USE SELF-CONTAINED BREATHING APPARATUS WITH FULL FACEPIECE. COOL CONTAINERS IN VICINITY WITH WATER

SPRAY.

Unusual Fire/Explosion Hazard: KEEP ALL IGNITION SOURCES AWAY. GROUND ALL CONTAINERS. VAPORS MAY TRAVEL TO SOURCE OF IGNITION AND CAUSE FLASHBACK. FIRE CAUSES ACID SMOKE AND/OR FUMES.

Spill Release Procedures: REMOVE ALL IGNITION SOURCES. SMALL SPILLS: TAKE UP WITH ABSORBENT MATERIAL. LARGE SPILLS: DAM AND RECOVER.

Handling and Storage Prec autions: AVOID HIGH TEMPERATURE AREA AND IGNITION SOURCES. ALL HANDLING EQUIPMENT SHOULD BE GROUNDED AND EXPLOSION PROOF. AVOID ALL PERSONAL CONTACT. Other Precautions: WASH THOROUGHLY AFTER HANDLING.

Respiratory Protection:USE APPROVED SELF-CONTAINED BREATHING APPARATUS IF NECESSARY. Ventilation:LOCAL EXHAUST: NECESSARY. MECHANICAL (GENERAL): NECESSARY. Protective Gloves:RUBBER OR NEOPRENE Eye Protection:CHEMICAL SP ALSH GOGGLES Other Protective Equipment:SAFETY SHOWER. EYE WASH STATION. Supplemental Safety and Health

Boiling Pt:B.P. Text:165F,74C Vapor Pres:85 @ 20C Vapor Density:2.4 Spec Gravity:0.86 (WATER=1) Evaporation Rate & amp; Reference:4.6 (BU AC=1) Solubility in Water:APPRECIABLE Appearance and Odor:CLEAR TO AMBER LIQUID, KETONE ODOR Percent Volatiles by Volume:86

====

Stability Indicator/Materials to Avoid:YES
STRONG OXIDIZING AGENTS
Stability Condition to Avoid:STRONG ACIDS OR OXIDIZERS, HIGH TEMPERATURES
Hazardous Decomposition Products:CARBON MONOXIDE, CARBON DIOXIDE, MISCELLANEOUS HYDROCARBON
Conditions to Avoid Polymerization:STRONG OXIDIZERS, ALL IGNITION SOURCES.

Waste Disposal Methods: ACCORDING TO STATE, FEDERAL, AND LOCAL REGULATIONS. HAZARDOUS WASTE CODE: F00 5, D001, U159, FLAMMABLE.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information t o their

particular situation.