

GENERAL CHEMICAL CORPORATION -- POTASSIUM HYDROXIDE, PELLETS (VARIOUS GRADES) --
6810-00-234-8366

===== Product Identification =====

Product ID: POTASSIUM HYDROXIDE, PELLETS (VARIOUS GRADES)

MSDS Date: 10/01/1986

FSC: 6810

NIIN: 00-234-8366

MSDS Number: BWFKT

=== Responsible Party ===

Company Name: GENERAL CHEMICAL CORPORATION

Address: 90 E HALSEY RD

Box: 1829

City: MORRISTOWN

State: NJ

ZIP: 07960-1829

Country

: US

Info Phone Num: 201-455-5630

Emergency Phone Num: 201-455-3700

CAGE: 0AU44

=== Contractor Identification ===

Company Name: GENERAL CHEMICAL CORPORATION

Address: 90 EAST HALSEY ROAD

Box: City: PARSIPPANY

State: NJ

ZIP: 07054

Country: US

Phone: 973-515-1840

CAGE: 0AU44

===== Composition/Information on Ingredients =====

Ingred Name: POTASSIUM HYDROXIDE (SARA III)

CAS: 1310-58-3

RTECS #: TT2100000

Fraction by Wt: 100%

Other REC Limits: NONE RECOMMENDED

OSHA PEL: C, 2 MG/M3

ACGIH TLV: C 2 MG/M

3; 9394
EPA Rpt Qty:1000 LBS
DOT Rpt Qty:1000 LBS

===== Hazards Identification =====

LD50 LC50 Mixture:TLV IS 2MG/M3 CEILING
Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:**CORROSIVE**EYES:MAY CAUSE IRRITATION
AND DAMAGE.SKIN:MAY CAUSE IRRITATION AND DAMAGE.INGEST:MAY CAUSE GI
TRACT IRRITATION.INHAL:MAY CAUSE RESPIRATORY IRRITATION.>200MG/M3
ARE IMMEDIA
TELY DANGEROUS A ND MAY CAUSE LUNG DAMAGE.
Explanation of Carcinogenicity:THERE ARE NO INGREDIENTS ABOVE 0.1%
WHICH ARE IDENTIFIED AS CARCINOGENS BY NTP,IARC OR OSHA.
Effects of Overexposure:INGEST:PAIN,DIFFICULT
BREATHING,VOMITING,DIARRHEA,COLLAPSE.
Medical Cond Aggravated by Exposure:PERSONS WITH PRE-EXISTING SKIN,EYE
AND RESPIRATORY AILMENTS MAY BE AT INCREASED RISK FROM EXPOSURE.

===== First Aid Measures =====

First Aid:SKIN:FLUSH UNDER DEL
UGE SHOWER WHILE REMOVING CONTAMINATED
CLOTHING;WASH WITH WATER(UNTIL "SOAPY" FEEL IS GONE).EYES:SPEED IS
ESSENTIAL.CALL FOR MEDICAL HELP;FLUSH WITH WATER FOR 15
MINUTES.INHAL:REMO VE TO FRESH AIR.GIVE OXYGEN OR ARTIFICIAL
RESPIRATION IF NEEDED.INGEST:DO NOT INDUCE VOMITING.GET PROMPT
QUALIFIED MEDICAL ATTENTION.IF CONSCIOUS,GIVE MILK OR WATER;THEN
VINEGAR OR FRUIT JUICE.

===== Fire Fighting Measures =====

Flash Point:NONE
Extinguishing
Media:USE MEDIA APPROPRIATE FOR SURROUNDING FIRE.
Fire Fighting Procedures:USE A SELF-CONTAINED BREATHING APPARATUS AND
FULL PROTECTIVE EQUIPMENT.
Unusual Fire/Explosion Hazard:THIS MATERIAL WILL REACT WITH
METALS(AL,SN,ZN) TO RELEASE HYDROGEN GAS.MAY VAPORIZE IN A
FIRE;MOISTURE CONTACT MAY CAUSE ENOUGH HEAT TO IGNITE COMBUSTIBLES.

===== Accidental Release Measures =====

Spill Release Procedures:SHOVEL INTO AN APPROPRIATE
CONTAINER.NEUTRALIZE ANY MO

ISTENED SPILL WITH ACETIC

ACID(PREFERRED) OR SODIUM BICARBONATE;SOAK UP WITH AN INERT
ABSORBANT;PLACE IN A SUITABLE CONTAINER.WASH SPILL AREA WITH WATER
TO REMOVE SLIPPERINESS;AVOID SEWER DISCHARG

Neutralizing Agent:ACETIC ACID IS PREFERRED.SODIUM BICARBONATE MAY BE
USED.

=====
===== Handling and Storage =====

Handling and Storage Precautions:STORE IN A COOL,DRY,WELL-VENTILATED
PLACE.KEEP CONTAINER CLOSED WHEN NOT IN USE.SEPERATE FROM MOISTURE,

INCOMPATIBLE MATERIALS AND COMBUSTIBLES.

Other Precautions:THIS ITEM SHOULD BE HANDLED ONLY BY TRAINED
PERSONNEL.FOLLOW LABEL DIRECTIONS.AVOID BREATHING VAPORS.AVOID SKIN
AND EYE CONTACT.DO NOT STORE THIS ITEM IN CONTAINERS MADE OF
FE,SN,AL,ZN METALS OR THEIR ALLOYS.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:WHERE ENVIRONMENTAL CONTROLS ARE LACKING OR IN
ENCLOSED SPACES USE EITHER A SELF-CONTAINED BREATHING APPARATUS OR

A NOISH/MSHA APPROVED RESPIRATOR FOR CORROSIVE GAS,DEPENDING ON THE
AIRBORN CONCENTRAT ION.

Ventilation:LOCAL VENTILATION AT THE WORKSITE;MECHANICAL(GENERAL)
VENTILATION TO MAINTAIN TLV/PEL.

Protective Gloves:RUBBER,NEOPRENE.

Eye Protection:CHEMICAL SPLASH GOGGLES.AVOID CONTACTS.

Other Protective Equipment:PROTECTIVE CLOTHING,AS NEEDED.PROVIDE A
LOCAL EYE WASH STATION AND SAFETY SHOWER.

Work Hygienic Practices:WASH HANDS.SEPERATE WORK CLOTHES FROM STREET
CLOTHES.LAUNDER WORK CLO

THES BEFORE REUSE.KEEP FOOD OUT OF THE WORK
AREA.

Supplemental Safety and Health

NONE

=====
===== Physical/Chemical Properties =====

HCC:B1

Boiling Pt:=1320.C, 2408.F

Melt/Freeze Pt:=360.C, 680.F

Spec Gravity:2.044

pH:13.5

Evaporation Rate & Reference:NEGLIGIBLE

Solubility in Water:APPRECIABLE

Appearance and Odor:PELLETS;WHITE;ODORLESS.THIS ITEM ABSORBS WATER.

Percent Volatiles by Volume:NEGLIG

=====
===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid: YES

METALS (AL, SN, ZN), ACIDS AND THEIR ANHYDRIDES, EASILY OXIDIZABLE
CMPDS (EXPLOSIVES, ALDEHYDES, NITRO AND CHLOROCARBONS).

Stability Condition to Avoid: MOISTURE, PROLONGED EXPOSURE TO AIR.

Hazardous Decomposition Products: CONTACT WITH METALS MAY GENERATE
H*2. REACTS WITH CO*2 TO FORM POTASSIUM CARBONATE.

===== Disposal Considerations =====

Waste Disposal Methods: DISPOSE OF IN ACCORDANCE WITH FEDERAL, STATE AND
LOCAL RE
GULATIONS. RCRA CODE IS D002 (CORROSIVE).

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this
information to their
particular situation.