

NUCLEAR RESEARCH CORP DOVER DIVISION -- B500599B -- 5960-00-448-7015

===== Product Identification =====

Product ID:B500599B

MSDS Date:01/01/1988

FSC:5960

NIIN:00-448-7015

MSDS Number: BXZGN

=== Responsible Party ===

Company Name:NUCLEAR RESEARCH CORP DOVER DIVISION

Address:RICHBOYNTON ROAD

City:DOVER

State:NJ

ZIP:07801

Country:US

Info Phone Num:201-361-5600

Emergency Phone Num:201-361-5600

Prepar

er's Name:DSCR-VBA STAFF

CAGE:06442

=== Contractor Identification ===

Company Name:NUCLEAR RESEARCH CORP DOVER DIVISION

Address:58 RICHBOYNTON RD

Box:937

City:DOVER

State:NJ

ZIP:07801

Country:US

Phone:973-361-5600

CAGE:06442

===== Composition/Information on Ingredients =====

Ingred Name:ARTICLE-ITEM IS AN ARTICLE, NO MSDS OR INGREDIENT DATA  
REQUIRED UNDER 29 CFR 1910.1200.

Other REC Limits:NONE RECOMMENDED

===== Hazards Identification =====

===

Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO  
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO  
Health Hazards Acute and Chronic:NO KNOWN HEALTH EFFECTS.  
Explanation of Carcinogenicity:NO INGREDIENT OF A CONCENTRATION OF 0.1%  
OR GREATER IS LISTED AS A CARCINOGEN OR SUSPECTED CARCINOGEN.  
Effects of Overexposure:NONE KNOWN.  
Medical Cond Aggravated by Exposure:NONE

=====  
===== First Aid Measures =====

First Aid:IF ANY SYMPTOMS OCCUR, SEE A DOCTOR

=====  
===== Fire Fighting Measures =====

Extinguishing Media:USE MEDIA APPROPRIATE FOR SURROUNDING FIRE.  
Fire Fighting Procedures:WEAR SELF-CONTAINED BREATHING APPARATUS AND  
FULL PROTECTIVE GEAR.  
Unusual Fire/Explosion Hazard:NONE

=====  
===== Accidental Release Measures =====

Spill Release Procedures:SWEEP UP AND DISCARD IN TRASH.  
Neutralizing Agent:NONE.

=====  
===== Handling and Storage =====

Handling and  
Storage Precautions:NO SPECIAL REQUIREMENTS.  
Other Precautions:NONE.

=====  
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NONE NORMALLY REQUIRED.  
Ventilation:NONE NORMALLY REQUIRED.  
Protective Gloves:NONE NORMALLY REQUIRED.  
Eye Protection:NONE NORMALLY REQUIRED.  
Other Protective Equipment:NONE NORMALLY REQUIRED.  
Work Hygienic Practices:WASH HANDS AFTER HANDLING AND BEFORE EATING,  
DRINKING, OR SMOKING. LAUNDRER CONTAMINATED CLOTHES BEFORE REUSE.  
Supplem

ental Safety and Health

MSDS GENERATED BY DLA-HMIS STAFF ITEM IS AN ARTICLE CONTAINING NO RADIOACTIVE MATERIALS PER MANUFACTURER'S REPRESENTATIVE 1/03/96, ELLEN. MSDS WAS GENERATED SIMPLY TO PROVIDE THE DOD END USERS INFORMATION FOR HEALTH & SAFETY REASONS ONLY. TESTING MAY BE REQUIRED FOR DISPOSAL.

===== Physical/Chemical Properties =====

HCC:N1

Appearance and Odor:ELECTRON TUBE.

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

NONE

Stability Condition to Avoid:NONE

Hazardous Decomposition Products:NONE

Conditions to Avoid Polymerization:WILL NOT OCCUR.

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL ENVIRONMENTAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of De

fense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.