View NSN Online: https://aerobasegroup.com/nsn/5960-01-074-6110

COMMUNICATION & PWR INDUSTRIES(FRMLY VARIAN ASSOC) -- VDU1067 ELECTRON TUBE --

Product ID:VDU1067 ELECTRON TUBE

MSDS Date:01/04/1996

FSC:5960

NIIN:01-074-6110
MSDS Number: BYHJT
=== Responsible Party ===

Company Name: COMMUNICATION & PWR INDUSTRIES (FRMLY VARIAN ASSOC)

Address: BEVERLY MICROWAVE DIV, 150 SOHIER RD

City:BEVERLY

State:MA ZIP:01915-55

95

Country:US

Info Phone Num:508-922-6000 EXT.285

Emergency Phone Num:508-922-6000 EXT.285

Preparer's Name: FRANK E. TROJAN

CAGE:KO568

=== Contractor Identification ===

Company Name: COMMUNICATION & PWR INDUSTRIES (FRMLY VARIAN ASSOC)

Address: BEVERLY MICROWAVE DIV, 150 SOHIER RD

City:BEVERLY

State:MA

ZIP:01915-5595 Country:US

Phone:508-922-6000 EXT.285

CAGE:KO568

Company Name: COMMUNICATIONS AND POWER INDUSTRIES INC

Address:150 SOHIER RD

City:BEVERLY

State:MA

ZIP:01915-5595

Country:US

Phone:978

-922-6000 EXT.285

CAGE:88236

======= Composition/Information on Ingredients ========

Ingred Name: NO INGREDIENT FOR THIS FORMULATION_INGREDIENT

=========== Hazards Identification ===============

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:THE TUBE IS CONSIDERED TO BE A SEALED SOURCE & NORMAL HANDLING WILL PRESENT NO RADIATION PROBLEMS.

ACUTE/CHRONIC OVERE

XPOSURE: SIGNIFICANT EXPOSURE TO A RADIONUCLIDE MAY CAUSE CANCER. BROKEN OR DISASS EMBLED RECEIVER PROTECTOR TUBES MAY EMIT IONIZING RADIATION. Explanation of Carcinogenicity: PER MSDS: CANCER CAUSING AGENT: NOT LISTED IN NTP/IARC/OSHA. Effects of Overexposure:TRITIUM IS A BETA EMITTER. IF EXPOSURE IS SUSPECTED SEEK MED ATTN, URINE ASSAY FOR TRITIUM IS THE ONLY MEANS OF MEASURING THE DEGREE OF EXPOSURE. Medical Cond Aggravated by Exposure: HEALING OF DAMAGED TISSUES MAY BE **PRO** LONGED. First Aid:SKIN CONTACT:FLUSH W/WATER FOR 15MINS. EYE CONTACT:FLUSH W/WATER FOR 15MINS. INHAL:REMOVE TO FRESH AIR. INGEST:A HIGH ORAL FLUID INTAKE SHOULD BE ADMINISTERED FOLLWOING TRITIUM EXPOSURE. Lower Limits:N/APPLICABLE Upper Limits:N/APPLICABLE ======== Accidental Release Measures ============ Spill Release Procedure s:WHEN HANDLING BROKEN TUBES WEAR PROTECTIVE RUBBER GLOVES/CLOTHING.AVOID POSSIBLITY OF RUBBING RADIOACTIVE MATL ONTO SKIN. WASH EXPOSED SKIN AFT HDNLG BRONEK TUBES CONTAINING RADIOACTIVE MATL.AVOID INHA L GASES FRM BROKEN TUBES CONTAINING TRITIUM.

============= Handling and Storage ==========================

Handling and Storage Precautions: PROPER USE/SAFE OPERATING PRACT W/RESPECT TO MICROWAVE TUBES/EQPMT ARE RESPONSIBLITY OF EQPMT MFG & USERS OF SUCH TUBES/EQPMT

.TAKE APPROPRIATE ACTION.

Other Precautions: ALL PERSONS WHO WORK W/OR ARE EXPO TO MICROWAVE TUBE/EQPMT WHICH UTILIZES SUCH TUBES MUST TAKE PRECAUT TO PROT THEMSELVES AGAINST POSSIBLE SER BODILY INJURY.DON'T BE CARELESS AROUND SUCH PRODUCTS.PROD SPEC CONTAINS OPERATING INFO/PRECAUTION

====== Exposure Controls/Personal Protection ========

Respiratory Protection: IF SPILLED, WEAR RADIONUCLIDE CARTRIDGE RESPIRATOR.

Ventilation: PLACE AFFECTED COMPONENT IN LOCAL EXHAUST

Protective Gloves: DISPOSABLE GLOVES. Eve Protection: GOGGLES. Work Hygienic Practices: WASH HANDS. CARELESS OPERATION OF THIS DEVICE CAN RESULT IN INJURY OR DEATH. Supplemental Safety and Health THIS DEVICE IS A RECEIVER PROTECTOR TUBE WHICH CONTAINS SMALL AMT OF TRITIUM.TUBE IS CONSIDERED TO BE SEALED SOURCE & NORMAL HNDLG WILL PRESENT NO RADIATION PROBLEMS. DEVICE IS A MFG ARTICLE IAW 49CFR1 73.422.DEVICE IS AN ARTICLE IAW 29CFR1910.1200.DEVICE IS AN ELECTRON TUBE MFG IN COMP LIANCE W/10CFR30.15(A)(8). ========= Physical/Chemical Properties =========== HCC:A1 NRC/State Lic Num:20-02237-04 Boiling Pt:B.P. Text:-248C @1ATM Melt/Freeze Pt:M.P/F.P Text:-420F,-251C Decomp Temp:Decomp Text:N/APPLICABL Vapor Pres:18.317 ATM Vapor Density:N/APPLICAB Spec Gravity:6.0 pH:N/APPL Solubility in Water:100%, COMPLETE Appearance and Odor: RECEIVER PROTECTOR TUBE W/SM AMT OF TRITIUM; SEALED; ARTICLE; GAS, NO ODOR. (SUPPLE Corrosion Rate:N/APPLIC Stability and Reactivity Data ========= Stability Indicator/Materials to Avoid:YES OXIDIZERS. Stability Condition to Avoid: TEMPERATURES IN EXCESS OF 400C WILL CAUSE DECOMPOSITION OF TIT2 W/RELEASE OF TRITIUM GAS. Hazardous Decomposition Products: UNBOUND TRITIUM. ======= Disposal Considerations ============ Waste Disposal Methods: DISPOSE OF BROKEN OR SPENT TUBES AS SPECIFIED IN 10 CFR PART 20 & 10 CFR PART 30. HAZ INGRED:TRITIUM (H3 OR T) AS TIT2, N

ORMAL-SOLID FORM, RADIOACTIVITY:50.0MICROCURIES, %:LESS THAN 1%. ANOTHER NCR LI C #:20-02237-03E.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.