View NSN Online: https://aerobasegroup.com/nsn/8040-00-728-2887 EPOXY TECHNOLOGY -- 310200 SILVER FLAKE -- 8040-00-728-2887 ============= Product Identification ======================== Product ID:310200 SILVER FLAKE MSDS Date:09/20/1993 FSC:8040 NIIN:00-728-2887 MSDS Number: BZXST === Responsible Party === Company Name: EPOXY TECHNOLOGY Address:14 FORTUNE DRIVE Box:567 City:BILLERICA State:MA ZIP:01821-3922 Country:US Info Phone Num:508-667-3805 Emergency Phone Num:508-667-3805 CAGE:33 246 === Contractor Identification === Company Name: EPOXY TECHNOLOGY Address:14 FORTUNE DRIVE Box:City:BILLERICA State:MA ZIP:01821 Country:US Phone:978-667-3805 CAGE:33246 ======= Composition/Information on Ingredients ======== Ingred Name:SILVER *96-2* CAS:7440-22-4

RTECS #:VW3500000
Fraction by Wt: 100%
OSHA PEL:0.01 MG/CUM
ACGIH TLV:0.1 MG/CUM

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

=========== Hazards Identification ==============

Routes of Entry: Inhalation:NO

Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:INHALATION: RESPIRATORY IRRITATION. SKIN: IRRITATION. PROLONGED/REPEATED EXPOSURE TO SILVER DUST CAN RESULT IN PNEUMOCONLOSIS &/PERMANENT SKIN PIGMENTATION (ARGYRIA). EYES: IRRITATION. Explanation of Carcinogenicity:NONE Effects of Overexposure:IRRITATION.
======================================
First Aid:EYES: FLUSH W/WATER. SKIN: CLEAN W/SOAP & WATER. DON'T USE SOLVENTS FOR CLEANING. OBTAIN MEDICAL ATTENTION IN ALL CASES.
============= Fire Fighting Measures ==============
Flash Point:>200F Fire Fighting Procedures:NONE Unusual Fire/Explosion Hazard:NON-FLAMMABLE.
========= Accidental Release Measures ==========
Spill Release Procedures:VACUUM/SWEEPUP DUST. FOLLOW GOOD HOUSEKEEPING PROCEDURES.
============= Handling and Storage ==============
Handling and Storage Preca utions:KEEP CONTAINERS CLOSED WHEN NOT IN USE. Other Precautions:AVOID CONTACT W/SKIN & EYES & BREATHING OF AIR BORN PARTICLES.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:WEAR A NIOSH APPROVED RESPIRATOR WHENEVER HIGH LEVEL EXPOSURE TO AIR BORN PARTICLES IS ANTICIPATED. Ventilation:LOCAL EXHAUST VENTILATION. Protective Gloves:IMPERVIOUS, NEOPRENE Eye Protection:CHEMICAL SPLASH GOGGLES, FACE SHIELD Other Protective Equipment:BARRIER CR

EAM, IMPERVIOUS APRON, SAFETY SHOWER, EYE WASH FACILITY. Work Hygienic Practices:WASH THOROUGHLY AFTER HANDLING. Supplemental Safety and Health

======== Physical/Chemical Properties ==========

Vapor Density:>1 Solubility in Water:INSOLUBLE Appearance and Odor:FINE SILVER POWDER W/MILD ODOR. Percent Volatiles by Volume: