

NORTH AMERICAN PROFESSIONAL PRODUCTS -- 6075, DRY FILM LUBRICANT, RI-274 --
9150-01-148-7155

===== Product Identification =====

Product ID: 6075, DRY FILM LUBRICANT, RI-274
MSDS Date: 01/02/1996
FSC: 9150
NIIN: 01-148-7155
MSDS Number: CBTFK
=== Responsible Party ===
Company Name: NORTH AMERICAN PROFESSIONAL PRODUCTS
Address: 1500 MCCONNELL RD
City: WOODSTOCK
State: IL
ZIP: 60098-7310
Country: US
Info Phone Nu
m: 800-766-7655
Emergency Phone Num: 800-255-3924
Preparer's Name: CHRISTINA S. SALAZAR
CAGE: 0T7G9
=== Contractor Identification ===
Company Name: NORTH AMERICAN PROFESSIONAL PRODUCTS
Address: 1500 MCCONNELL RD
Box: City: WOODSTCK
State: IL
ZIP: 60098-7310
Country: US
Phone: 815-648-2424/800-766-7655
CAGE: 0T7G9

===== Composition/Information on Ingredients =====

Ingred Name: ISOBUTANE
CAS: 75-28-5
RTECS #: TZ4300000
Fraction by Wt: 11-30%
Other REC Limits: NONE RECOMMENDED

Ingred Name: PROPA

NE
CAS:74-98-6
RTECS #:TX2275000
Fraction by Wt: 11-30%
Other REC Limits:NONE RECOMMENDED
OSHA PEL:1000 PPM
ACGIH TLV:ASPHYXIAN; 9596

Ingred Name:ISOPROPYL ALCOHOL (SARA 313)
CAS:67-63-0
RTECS #:NT8050000
Fraction by Wt: 1-10%
Other REC Limits:NONE RECOMMENDED
OSHA PEL:400 PPM
ACGIH TLV:400 PPM/500STEL;9596

Ingred Name:ACETONE (SARA 313) (CERCLA)
CAS:67-64-1
RTECS #:AL3150000
Fraction by Wt: 51-70%
Other REC Limits:NONE RECOMMENDED
OSHA PEL:1000 PPM
ACGIH TLV:750PPM/1000STEL;9596
EPA Rpt Qty:
5000 LBS
DOT Rpt Qty:5000 LBS

=====
===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:EYES:MAY CAUSE IRRITATION.SKIN:MAY
CAUSE IRRITATION.INGEST:MAY CAUSE GI TRACT IRRITATION.ASPIRATION
HAZARD.SPIRATORY IRRITATION.CHRONIC:MAY DAMAGE LUNGS.
Explanation of Carcinogenicity:THERE ARE NO INGREDIENTS ABOVE 0.1%
WHICH ARE IDENTIFIED AS
CARCINOGENS BY NTP,IARC OR OSHA.
Effects of
Overexposure:EYES:PAIN.SKIN:DERMATITIS.INHAL:DIZZINESS,NAUSEA,LIGHT
HEADEDNESS,HEADACHE.
Medical Cond Aggravated by Exposure:PERSONS WITH PRE-EXISTING
RESPIRATORY AILMENTS MAY BE AT INCREASED RISK FROM EXPOSURE.

=====
===== First Aid Measures =====

First Aid:SKIN:REMOVE CONTAMINATED CLOTHING;WASH WITH SOAP AND
WATER.EYES:FLUSH WITH WATER FOR 15 MINUTES.INHAL:REMOVE TO FRESH
AIR.GIVE OXYGEN OR ARTIFI

CIAL RESPIRATION IF NEEDED.INGEST:DO NOT
INDUCE VOMITING. GET PROMPT QUALIFIED MEDICAL ATTENTION.IF
CONSCIOS,GIVE PLENTY OF WATER TO DRINK.

===== Fire Fighting Measures =====

Flash Point: