View NSN Online: https://aerobasegroup.com/nsn/6135-01-275-1363

DURACELL INC -- 7K67 ALKALINE MANGANESE DIOXIDE CELL -- 6135-01-275-1363

Product ID:7K67 ALKALINE MANGANESE DIOXIDE CELL

MSDS Date:01/17/1994

FSC:6135

NIIN:01-275-1363

MSDS Number: CDCKW
=== Responsible Party ===
Company Name: DURACELL INC

Address:BERKSHIRE INDUSTRIAL PK BLDG 9

City:BETHEL State:CT

ZIP:06801-5000 Country:US

Info Phone Num:203-796-4292/617-449-760

U

Emergency Phone Num:203-796-4292/617-449-7600

CAGE:GO384

=== Contractor Identification === Company Name: DURACELL INC

Address: BERKSHIRE INDUSTRIAL PK BLDG 9

City:BETHEL State:CT

ZIP:06801-5000

Country:US

Phone:203-796-4292/617-449-7600

CAGE:GO384

Company Name: DURACELL INC TECHNICAL SALES AND MARKETING GROUP

Address:BERKSHIRE CORPORATE PARK

Box:City:BETHEL

State:CT ZIP:06801 Country:US

Phone:203-796-4000

CAGE:90303

======= Composition/Information on Ingredients ========

Ingred Na

me:POTASSIUM HYDROXIDE

CAS:1310-58-3

RTECS #:TT2100000 Fraction by Wt: 8%

Other REC Limits: 2 MG/CUM (CEILING)

OSHA PEL:2 MG/CUM (CEILING) ACGIH TLV:2 MG/CUM (CEILING)

EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:MANGANESE DIOXIDE, MANGANESE PEROXIDE *96-4*

CAS:1313-13-9

RTECS #:OP0350000 Fraction by Wt: 37% OSHA PEL:5 MG/CUM ACGIH TLV:5 MG/CUM

Ingred Name:ZINC CAS:7440-66-6

RTECS #:ZG8600000 Fraction by Wt: 15% OSHA PEL:15 MG/CUM ACGIH TLV:10 MG/CUM EPA Rpt Qty:1000 LBS

DOT Rpt Qty:1

000 LBS

Ingred Name:WATER

CAS:7732-18-5

RTECS #:ZC0110000 Fraction by Wt: 11%

Ingred Name: CARBON, ACTIVATED CARBON, GRAPHITE

CAS:7440-44-0

RTECS #:FF5250100 Fraction by Wt: 4%

OSHA PEL:3.5 10 MG/CUM ACGIH TLV:3.5 MG/CUM

Ingred Name:STEEL Fraction by Wt: 18% OSHA PEL:10 MG/CUM ACGIH TLV:10 MG/CUM

Ingred Name:BRASS Fraction by Wt: 2% OSHA PEL:10 MG/CUM ACGIH TLV:10 MG/CUM

Ingred Name:PLASTIC Fraction by Wt: 4%

Ingred Name: PAPER, SILICA GEL

Fraction by Wt: 1%

Ingred Name: MERCURY, QUICKSILVER

Other REC Limits:INORGANIC 0.1 MG/CUM OSHA PEL:0.05 MG/CUM ACGIH TLV:0.01 MG/CUM (SKIN)
EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB
======================================
Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:THESE CHEMICALS ARE CONTAINED IN A SEALED CAN. RISK OF EXPOSURE OCCURS ONLY IF BATTERY IS
MECHANICALLY, PHYSICALLY/ELECTRICALLY ABUSED. SKIN & EYE CONTACT W/POTASSIUM HYDROXIDE MAY CAUSE CHEMICAL BURN S & PERMANENT EYE INJURY.
Explanation of Carcinogenicity:NONE Effects of Overexposure:CHEMICAL BURNS.
======================================
First Aid:SKIN/EYES: IMMEDIATELY FLUSH W/COPIOUS AMOUNTS OF WATER FOR 15 MINS. OBTAIN MEDICAL ATTENTION IN ALL CASES.
======================================
Fire Fighting Procedures:WEAR SCBA WHEN A LARGE NUMBER OF CELLS ARE INVOLVED IN A FIRE.
Unusual Fire/Explosion Hazard:CELLS MAY RELEASE TOXIC ZINC FUMES WHEN EXPOSED TO FIRE.
======================================
Spill Release Procedures:AVOID SKIN & EYE CONTACT.
======================================
Handling and Storage Precautions:STORE AT ROOM TEMP. AVOID SKIN & EYE CONTACT. DON'T ATTEMPT TO RECHARGE. INSTALL CELLS IAW/EQUIPMENT

(IARC CARCINOGEN GROUP 3) *96-4* CAS:7439-97-6

RTECS #:OV4550000

INSTRUCTIONS. DON'T DISPOSE OF IN FIRE. Other Precautions: REPLACE ALL BATTERIES IN EQUIPMENT AT SAME TIME. DON'T MIX BATTERY SYSTEMS SUCH AS ALKALINE & ZINC CARBON IN SAME EQUIPMENT. DON'T CARRY BATTERIES LOOSE IN POCKET/BAG. ===== Exposure Controls/Personal Protection ======== Respiratory Protection: SCBA WHEN LARGE NUMBERS OF CELLS ARE INVOLVED IN A FIRE. Ventilation: SUBSEQUENT TO FIRE, PROVIDE AS MUCH VENTILATION AS POSSIBLE. Protective Gloves: NEOPRENE, RUBBE R/LATEX-NITRILE Eve Protection: SAFETY GLASSES Other Protective Equipment: NONE Supplemental Safety and Health MSDS INFORMATION IS FOR MANGANESE DIOXIDE. ======== Physical/Chemical Properties =========== Melt/Freeze Pt:M.P/F.P Text:995F Spec Gravity:5 Solubility in Water:0% Appearance and Odor:BLACK POWDER ======== Stability and Reactivity Data ========== Stability Indicator/Materials to Avoid:YES Stability Condition to Avoid: HEAT, DISASSEMBLY, RECHARGE, MECHANICAL/PHYSICAL/ELECTRICAL ABUSE, HIGH TEMPS, FIRE. Hazardous Decomposition Products: WHEN HEATED: HAZARDOUS FUMES OF ZINC & CAUSTIC POTASSIUM HYDROXIDE. ======= Disposal Considerations ============

Waste Disposal Methods:SMALL QUANTITIES: DISPOSE OF W/HOUSEHOLD TRASH. LARGE QUANTITIES: TREAT AS IF A HAZARDOUS WASTE. DON'T INCINERATE SINCE CELLS MAY EXPLODE AT EXCESSIVE TEMPS. DISPOSE OF IAW/FEDERAL, STATE & LOCAL REGU LATIONS.

Disclaimer (provided

with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.