View NSN Online: https://aerobasegroup.com/nsn/9150-01-052-7562

ANDEROL COMPANY -- ANDEROL 500 SYNTHETIC COMPRESSOR OIL, 0810500 -- 9150-01-052-7562

Product ID: ANDEROL 500 SYNTHETIC COMPRESSOR OIL, 0810500 MSDS Date:03/26/1996 FSC:9150 NIIN:01-052-7562 Status Code:A MSDS Number: CJKPC === Responsible Party === Company Name: ANDEROL COMPANY Address:215 MERRY LANE **City:EAST HANOVER** State:NJ ZIP:07936 Country:US Info Phone Num:9 08-738-3517 Emergency Phone Num:908-738-3517 CAGE:TO156 === Contractor Identification === Company Name: ANDEROL COMPANY Address:215 MERRY LANE Box:City:EAST HANOVER State:NJ ZIP:07936 Country:US Phone:973-887-7411 CAGE:TO156 Company Name: ROYAL LUBRICANTS COMPANY INC. Address:215 MERRY LN Box:518 **City:EAST HANOVER** State:NJ ZIP:07936 Country:US Phone:973-887-7411/7410 Contract Num:SP0450-99-M-B124 CAGE:07950

Ingred Name:N-PHENYL

-1-NAPHTHYLAMINE CAS:90-30-2 RTECS #:QM4500000 Other REC Limits:NONE RECOMMENDED

Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:TARGET ORGANS: NOT PROVIDED. LOW HAZARD FOR USUAL INDUSTRIAL HANDLING. POTENTIAL HEALTH EFFECTS: EYE CONTACT: NO HAZARD EXPECTED IN NORMAL USE. SKIN CONTACT: NO HAZARD EXPECTED IN NORMAL USE. INHAL

ATI ON: NO HAZARD EXPECTED IN NORMAL USE. INGESTION: NO HAZARD EXPECTED IN NORMAL USE. Explanation of Carcinogenicity:NONE

Effects of Overexposure:NO HAZARD EXPECTED IN NORMAL USE.

First Aid:INHALATION: REMOVE TO FRESH AIR. IF NOT BREATHING, GIVE CPR. IF BREATHING IS DIFFICULT, GIVE OXYGEN. GET IMMEDIATE MEDICAL ATTENTION. EYE CONTACT: IN CASE OF CONTACT, IMMEDIATELY FLUSH EYES WITH PLENT Y OF WATER FOR. OBTA

IN MEDICAL ATTENTION IF IRRITATION

DEVELOPS OR PERSISTS. SKIN CONTACT: REMOVE CONTAMINATED CLOTHING. WASH SKIN THOROUGHLY WITH SOAP AND WATER. IF IRRITATION DEVELOPS AND PERSISTS, CONSULT A PHYSICIAN. LAUNDER CLOTHING BEFORE REUSE. INGESTION: NO ADVERSE EFFECTS EXPECTED BY THIS ROUTE OF EXPOSURE. IF SYMPTOMS DEVELOP, GET MEDICAL ATTENTION.

Flash Point Method:COC
Flash Point:=248.9C, 480.F
Extinguishing Me
dia:WATER SPRAY OR FOG, FOAM, CARBON DIOXIDE OR DRY
CHEMICAL.
Fire Fighting Procedures:AS WITH ANY FIRE, WEAR PROTECTIVE CLOTHING AND
NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS TO AVOID
INHALATION OF HAZARDOUS DECOMPOSTION PRODUCTS OR SMOKE.
Unusual Fire/Explosion Hazard:CONTAINERS MAY BURST DUE TO EXTREME
HEAT;COOL WITH WATER SPRAY.FIRE OR EXCESSIVE HEAT MAY CAUSE

PRODUCTION OF HAZARDOUS DECOMPOSITION PRODUCTS.

======= Accidental Release Measures =======

\_\_\_\_\_

Spill Release Procedures: VENTILE AREA. ABSORB SPILL WITH INERT MATERIAL AND PLACE IN A CHEMICAL WASTE CONTAINER. OBEY RELEVANT LOCAL, STATE AND FEDERAL LAWS AND REGULATIONS. DO NOT CONTAMINATE ANY LAKES, STREAMS, PONDS, GROUN DWATER OR SOIL. USE PERSONAL PROTECTIVE EQUIPMENT AS DESCRIBED IN MSDS..

Handling and Storage Precautions: STORE IN A COOL, DRY PLACE. KEEP CONTAINERS CLOSED WHEN NOT IN US

Ε.

Other Precautions:WASH THOROUGHLY AFTER HANDLING. USE WITH ADEQUATE VENTILATION. AVOID BREATHING VAPOR OR MIST. AVOID CONTACT WITH EYES, SKIN AND CLOTHING.

Respiratory Protection:A RESPIRATORY PROTECTION PROGRAM THAT MEETS OSHA 1910.134 AND ANSI Z88.2 REQUIREMENTS MUST BE FOLLWED WNENEVER WORKPLACE CONDITIONS WARRANT A RESPIRATOR'S USE. Ventilation:ADEQUATE Protective Gloves:IMPERMEABLE Eye Protection:SAFETY GLASSES WITH SIDE SHIELDS Other Protective Equipment:INACCORDANCE WITH OSHA PPE STANDARD (29 CFR 1910.132). EYE WASH STATION AND SAFETY SHOWER,WORK CLOTHING AND APRON. Work Hygienic Practices:OBSERVE GOOD INDUSTRIAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES. WASH BEFORE EATING, DRINKING OR SMOKING. Supplemental Safety and Health NONE

HCC:V6 Boiling Pt:>348.9C, 660.F Melt/Freeze Pt:=-34.4C, -30.F M.P/F.P Text:P OUR POINT Vapor Pres:1 Spec Gravity:0.96 Evaporation Rate & Reference: