Address:1020 KING GEORGE POST ROAD City:FORDS State:NJ ZIP:08863 Country:US

Info Phone Num:732-738-3570

Company Name: HATCO CORP

Emergency Phone Num

:908.738.1000

Resp. Party Other MSDS Num.:1993066 REV 3

Chemtrec Ind/Phone:(800)424-9300

CAGE:0H3M4

=== Contractor Identification === Company Name: HATCO CORP

Address:1020 KING GEORGE POST ROAD

Box:City:FORDS

State:NJ ZIP:08863 Country:US

Phone:908-738-3517

Contract Num: SP0450-99-D-4024

CAGE:0H3M4

======= Composition/Information on Ingredients ========

Ingred Name:PENTAERYTHRITOL TETRAESTERS WITH MIXED FATTY ACIDS Other REC Limits:TLV 5 MG/M3

====== Hazards Identif

ication ====================================
Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:MAY BE AN EYE OR SKIN IRRITANT. LOW TO MEDIUM IN TOXICITY. Effects of Overexposure:NONE KNOWN. Medical Cond Aggravated by Exposure:NONE KNOWN.
======================================
First Aid:EYE CONTACT: FLUSH WTIH WTER FOR 15 MIN. SEE PHYSICIAN. SKIN: WASH WITH SOAP AND WATER THORO UGHLY. SEE PHYSICIAN IF NECESSARY. REMOVE CONTAMINATED CLOTHING. INGESTION: DO NOT INDUCE VOMITING. DRINK PLENTY OF WATER. DO NOT GIVE ANYTHING TO AN UNCONSCIOUS VICTIM. SEE PHYSICIAN IMMEDIATELY. INHALATION: REMOVE TO FRESH AIR. SEE PHYSICIAN IF NECESSARY.
======================================
Flash Point Method:COC Flash Point:=246.1C, 475.F MINIMUM Extinguishing Media:FOAM, CO2, DRY CHEMICAL. USE WATER SPRAY TO COOL SURFACE OR CONTAINER.
Fire Fighting Procedures:USE SELF-CONTAINED BREATHING APPARATUS, AVOID BREATHING FUMES, VAPORS, OR MISTS. WATER MAY CAUSE FROTHING. Unusual Fire/Explosion Hazard:NONE.
========= Accidental Release Measures ==========
Spill Release Procedures:DIKE OR CONTAIN SPILL. APPLY ABSORBENT. PUT IN CONTAINER, CLOSE CONTAINER. PREVENT FROM GOING INTO SEWER AND WATERWAYS. NOTIFY PROPER AUTHORITIES.
======================================
Handlin

g and Storage Precautions:FOR INDUSTRIAL USE ONLY. STORE IN COOL DRY PLACE.
====== Exposure Controls/Personal Protection ========
Respiratory Protection: USE NIOSH APPROVED ORGANIC VAPOR CARTRIDGE RESPIRATOR.
Ventilation:USE LOCAL EXHAUST/MECHANICAL (GENERAL) EXHAUST. Protective Gloves:NEOPRENE Five Protection:CUEMICAL SPLASH COCCLES
Eye Protection:CHEMICAL SPLASH GOGGLES Other Protective Equipment:NEOPRENE APRON. LONG SLEEVED SHIRT AND PANTS. SAFETY SHOES, HARD HAT. SAFETY SHOWER AND EYEWASH STATION. Work H
ygienic Practices:WASH WITH SOAP AND WATER AFTER CONTACT. AVOID INGESTION. PRACTICE GOOD PERSONAL HYGIENE. Supplemental Safety and Health
NA The state of th
======================================
HCC:V5 Spec Gravity:0.99-1.10@60F Evaporation Rate & Reference:NA Solubility in Water:@25 C: