View NSN Online: https://aerobasegroup.com/nsn/9150-00-985-7099

Product ID:HATCOL 3212 (MIL-PRF-23699F/CI) MSDS Date:09/22/1999 FSC:9150 NIIN:00-985-7099 Status Code:A MSDS Number: CKVKM === Responsible Party === Company Name:HATCO CORP Address:1020 KING GEORGE POST ROAD **City:FORDS** State:NJ ZIP:08863 Country:US Info Phone Num:732-738-1000 **Emergency Phone Num:7** 32-738-1000 Resp. Party Other MSDS Num.: 1993066 REVISION NUMBER 4 CAGE:0H3M4 === Contractor Identification === Company Name: HATCO CORP Address:1020 KING GEORGE POST ROAD Box:City:FORDS State:NJ ZIP:08863 Country:US Phone:908-738-3517 Contract Num:SP0450-99-D-4024 CAGE:0H3M4 Company Name: RADIAN INTL LLC Address:8501 N MOPAC BLVD Box:201088 City:AUSTIN State:TX ZIP:78720-1088 Country:US Phone:512-419-5224 Contract Num:SP0450-00-D-4021 CAGE:29913

======= Composition/Information on Ingredien

Ingred Name:PENTAERYTHRITOL TETRAESTERS WITH MIXED FATTY ACIDS Other REC Limits:5 MG/M3 HATCO

LD50 LC50 Mixture:NOT PROVIDED BY MANUFACTURER Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:MAY BE AN EYE OR SKIN IRRITANT. LOW TO MEDIUM IN TOXICITY. Explanation of Carcinogenicity:NO. Effects of Overexposure:NON E KNOWN. Medical Cond Aggravated by Exposure:NONE KNOWN

First Aid:EYE CONTACT: FLUSH WITH WATER FOR 15 MINUTES. SEE PHYSICIAN. SKIN CONTACT: WASH WITH SOAP AND WATER THOROUGHLY. SEE PHYSICIAN IF NECESSARY. REMOVE CONTAMINATED CLOTHING. INGESTION: DO NOT INDUCE V OMITING. DRINK PLENTY OF WATER. DO NOT GIVE ANYTHING TO AN UNCONSCIOUS VICTIM. SEE PHYSICIAN IMMEDIATELY. INHALATION: REMOVE TO FRESH AIR. SEE PHYSICIAN IF NECESSARY.

Flash Point Method:COC
Flash Point:>246.1C, 475.F
MINMUM 475F
Extinguishing Media:FOAM, CO2,DRY CHEMICAL. USE WATER SPRAY TO COOL SURFACE OF CONTAINER.
Fire Fighting Procedures:USE SILF-CONTAINED BREATHING APPARATUS, AVOID BREATHING FUMES, VAPORS, OR MISTS. WATER MAY CAUSE FROTHING.
Unusual Fire/Explosion Hazard:NONE, BUT AVOID CONTACT WITH FIRE AND SPARKS.

====== Accidental

Release Measures =============

Spill Release Procedures:DIKE OR CONTAIN SPILL. APPLY ABSORBENT. PUT IN CONTAINER, CLOSE CONTAINER. PREVENT FROM GOING INTO SEWER AND WATERWAYS. NOTIFY PROPER AUTHORITIES. Neutralizing Agent:NOT PROVIDED BY MANUFACTURER

Handling and Storage Precautions: FOR INDUSTRIAL USE ONLY. STORE IN COOL DRY PLACE.

======= Exposure Controls/Personal Protection ==========

Respir

atory Protection: USE NIOSH APPROVED ORGANIC VAPOR CARTRIDGE RESPIRATOR.

Ventilation:LOCAL EXHAUST: YES MECHANICAL (GENERAL) EXHAUST: YES Protective Gloves:NEOPRENE

Eye Protection: CHEMICAL SPLASH GOGGLES

Other Protective Equipment:NEOPRENE APRON. LONG SLEEVED SHIRT AND PANTS. SAFETY SHOES, HARD HAT. SAFETY SHOWER AND EYEWASH STATION. Work Hygienic Practices:WASH WITH SOAP AND WATER AFTER CONTACT. AVOID INGESTION. PRACTICE GOOD PERSONAL HYGIENE.

Supplemental Safety and Health

===

HCC:V6 Spec Gravity:0.99-1.10@60F Solubility in Water: