## NSN 1560-01-440-3491

Longeron Repair Kit - Page 1 of 1

A23800



View Online at https://aerobasegroup.com/nsn/1560-01-440-3491

| End Application:   |
|--|
| F-5e aircraft  |
| Special Features:  |
| Repair kit-f-5e fwd upr longeron (thin) replacement; contains aircraft parts and expendable tools to replace 6-10304 lh & rh upper cockpit |
| longerons  |
| Shelf Life:  |
| N/a  |
| Unit Of Measure:   |
| <del></del>  |
| Demilitarization:  |
| Yes - demil/mli  |
| Fiia:  |