NSN 1680-01-611-9405

Repair Blade Patch - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/1680-01-611-9405

D		٦.	ıct	NI.		٠.
_	ГО	m	ICT	N	am	Δ.

Leading edge abrasion strip rotor blade repair patch

Special Features:

Consists of 1-12.1 inch lg by 4.1 inch wd titanium repair patch and adhesive primer; opposite -101

General Description:

Opposite -101

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

Yes - demil/mli