

View Online at <https://aerobasegroup.com/nsn/2520-00-319-0295>

**Unable To Decode:**

Unable to decode and unable to decode

**Unable To Decode:**

Unable to decode and unable to decode

**Overall Length:**

Between 2.800 inches and 2.810 inches

**Bolt Circle Diameter:**

Err-070

**Unable To Decode:**

Unable to decode and unable to decode

**Mounting Hole Diameter:**

Err-070

**Overall Diameter:**

Err-070

**Bore Length:**

2.250 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Hub Length:**

1.500 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Bore Style (non-core):**

Err-090

**Shaft Facility Spline Quantity:**

10

**Fsc Application Data:**

Transmission to transfer case propeller shaft, truck chassis

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fig:**

A521s0