

View Online at <https://aerobasegroup.com/nsn/2520-00-319-0296>

Unable To Decode:

Unable to decode and unable to decode

Unable To Decode:

Unable to decode and unable to decode

Overall Length:

3.6875 inches

Unable To Decode:

Unable to decode and unable to decode

Flange Thickness:

0.3750 inches

Unable To Decode:

Unable to decode and unable to decode

Unable To Decode:

Unable to decode and unable to decode

Bore Length:

3.000 inches

Unable To Decode:

Unable to decode and unable to decode

Hub Length:

2.500 inches

Unable To Decode:

Unable to decode and unable to decode

Bore Style (non-core):

Err-090

Shaft Facility Spline Quantity:

10

Fsc Application Data:

Transfer case, truck chassis

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fig:

A521s0