

View Online at <https://aerobasegroup.com/nsn/2520-00-374-2138>

**Unable To Decode:**

Unable to decode and unable to decode

**Unable To Decode:**

Unable to decode and unable to decode

**Overall Length:**

Between 3.737 inches and 3.747 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Unable To Decode:**

Unable to decode and unable to decode

**Unable To Decode:**

Unable to decode and unable to decode

**Unable To Decode:**

Unable to decode and unable to decode

**Bore Length:**

3.000 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Hub Length:**

1.9062 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Bore Style (non-core):**

Err-090

**Shaft Facility Spline Quantity:**

10

**Special Features:**

Dirt-liquid deflector included

**Fsc Application Data:**

Rear axle assembly, truck chassis

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fiig:**

A521s0