

View Online at <https://aerobasegroup.com/nsn/2530-01-031-3197>

Fabrication Method:

Molded

Segment Quantity:

2

Features Provided:

Friction lining

Actuation Method And Location:

Hydraulic cylinder internal

Supplementary Features:

This item has been reviewed for asbestos material. The current approved source, 50737, has indicated their part number contained asbestos prior to 1984. They continue to manufacture the same part number without asbestos material after 1984

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fig:

A230a0