## NSN 2540-00-454-5129

Loaders Station Step - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/2540-00-454-5129

_		_			
(2an	arai	Desc	rint	ion.	•

No

Step is a gusset, fscm 19207, p/n11626537-2, welded to a step, fscm 19207, p/n 11626537-1 using fscm 96906, p/n ms27128-9, nut for	ρf
securing the apper right corner; step is 7.120 inches wide by 3.500 inches deep	

Step is a gusset, fscm 19207, p/n11626537-2, welded to a step, fscm 19207, p/n 11626537-1 using fscm 96906, p/n ms27128-9, nut fof
securing the apper right corner; step is 7.120 inches wide by 3.500 inches deep
Shelf Life:
N/a
Unit Of Measure:
Demilitarization: