NSN 3030-01-603-0395

Positive Drive Belt - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/3030-01-603-0395

•			
Specia	I LOS	otiir/	ac.
SUCCIO		atui	⊏ 3.

Emergency drive belt replacement kit; contains	136 tooth spliced belt,	alignment fixture block,	allen wrenches,	hardware and instructions;			
designed to temporarily replace harley davidson 1996 flt tour glide international police model motorcycle secondary drive belt							

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fiig:

A228b0