NSN 3465-01-418-7660

Rivet Hole Drilling And Locating Fixture - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/3465-01-418-7660

_		_	
Cn.	acial	Engl	tures:
JU	ELIA	геа	iui es.

Drill-rear compressor stator sync ring bumper. Required to drill rivet holes in replacement bumpers in proper alignment with existing holes in respective sync rings

Shelf Life:		
N/a		
Unit Of Measure:		
Demilitarization:		

Fiig:

No

A51000