

View Online at <https://aerobasegroup.com/nsn/4420-00-006-1963>

Product Name:

Repair kit, condenser

General Description:

Tube cutter part no. Y-3229/6.219 in. O/a lg/0.375 in. Sq drive, tube wall reducing tool-rough part no. Y-2900/3.375 in. O/a lg/0.558 in. Cutter dia/0.375 in. Sq drive, tube wall reducing tool-finishing part no. Y-2901/3.375 in. O/a lg/0.590 in. Cutter dia/0.375 in. Sq drive, tube removal tool part no. Y-2379/6.156 in. O/a lg/0.580 in. Diameter to 0.518 in. Diameter taper with 4 straight flutes/0.375 in. Sq drive, deburring tool part no. Y-2778/0.515 in. Plus 0.000 in. Minus 0.005 in. Cutter dia/0.375 in. Sq drive, permanent tube plug part no. Y-3250/5.563 in. O/a lg/0.625 in. Od of large end/0.468 in. Od of small end, special expander part no. Y-3251 with set of spare rollers/16, 688 in. O/a lg/0.368 in. Od with 1.250 in. Effective roller lg/0.375 in. Sq drive, expander part no. 41-c-07/7.531 o/a lg/0.375 in. Sq drive, 12 in. Extension universal joint part no. 20001/0.375 in. Sq male and female ends, power attachment adapter part no. 20214/2.500 in. O/a lg/0.875 in. Od with 0.375 in. Female dri

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No