

View Online at <https://aerobasegroup.com/nsn/5120-01-368-6696>

End Application:

Turbofan engine, f100-pw-100/200/220/220e/229

Functional Description:

Due to the increased tight fit in the no.4 bearing area between the seal and hpc shaft, a new tool is needed to overcome this fit during installation and removal

Supplementary Features:

Nairseal is heated and placed on shaft, tool detail is threaded onto shaft and reacts against jaws, contacting airseal; tool is hydraulically actuated; current tooling, pwa50981 will not work due to increase tight fit

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

Yes - demil/mli

Fiig:

T294-m