

View Online at <https://aerobasegroup.com/nsn/5120-01-368-6696>

**End Application:**

Turbofan engine, f100-pw-100/200/220/220e/229

**Functional Description:**

Due to the increased tight fit in the no.4 bearing area between the seal and hpc shaft, a new tool is needed to overcome this fit during installation and removal

**Supplementary Features:**

Nairseal is heated and placed on shaft, tool detail is threaded onto shaft and reacts against jaws, contacting airseal; tool is hydraulically actuated; current tooling, pwa50981 will not work due to increase tight fit

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

Yes - demil/mli

**Fiig:**

T294-m