

View Online at <https://aerobasegroup.com/nsn/5180-01-159-7784>

**Supply Items And Quantities:**

5120-01-208-8427 torque adapter 1; 5120-01-208-8428 torque adapter 1; 5120-01-213-2782 seal puller 1; 4920-01-013-1740 1

**Nonsupply Items And Quantities:**

3all p/ns have 99167 fscms; lts36894 or 737868-4 locator; wcs36117 or 737868-7 adapter; wcs36895 or 737868-6 adapter; 97-1466 or 737868-8 driver; aks36893 or 737868-1 bullet; hhs23589 or 737868-2 fixture; hus25757 or 737868-3; pws23590 or 737868-5 puller; bms39088 or 737868-10 bushing; fds39171 or 737868-11 fixture; djs39090 or 737868-9 driver; t62-63721 or 737868-12 arbor; 6sv87086 or 737868-14 driver; dms36841 or 737868-13 driver, 737970 fixture; 737971 fixture; 97-1454 adapter; 97-1453 adapter; 97-1460 adapter

**Special Features:**

U/o f101 engine

**Reference Number Differentiating Characteristics:**

As differentiated by source control reparable item

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fig:**

A23800