NSN 5210-01-525-8349

Gage Block - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/5210-01-525-8349

End	Δ	nı	nli	ca	tic	'n.
LIIU	\boldsymbol{n}	v	UII	ca	uч	,,,,

Master, inspection-3rd and 4th stage turbine disk

Criticality Code Justification:

Feat

Special Features:

F100-pw-100/200/220/220e, pwa500521 inspection gage consists of a rectangular steel gage body extension, and aslide sub-assembly assembly with six socket head screws. The inspection gagecontains a retractable pin and adjustable hand knob for adjusting the size of the gage. The pwa500517 and pwa50018constraint fixtures are used to constrain the 3rd and 4th stage turbine disks during dimensional inspection of the disk. Serd 9865

She		

N/a

Unit Of Measure:

__

Demilitarization:

No

Fiig:

T299-t