

View Online at <https://aerobasegroup.com/nsn/5210-01-525-8349>

End Application:

Master, inspection-3rd and 4th stage turbine disk

Criticality Code Justification:

Feat

Special Features:

F100-pw-100/200/220/220e, pwa500521 inspection gage consists of a rectangular steel gage body extension, and a slide sub-assembly assembly with six socket head screws. The inspection gage contains a retractable pin and adjustable hand knob for adjusting the size of the gage. The pwa500517 and pwa50018 constraint fixtures are used to constrain the 3rd and 4th stage turbine disks during dimensional inspection of the disk. Serd 9865

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fig:

T299-t