NSN 5210-01-539-7547

External Indicating Gage - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/5210-01-539-7547

End	Δn	nlic	atio	n·
LIIU	Αþ	piic	auo	11.

Test procedure. Oc&tc/lio atmosphere sampling

Criticality Code Justification:

Zzzy

Product Name:

Drawing) gauge (0-100 psi)

Reference Number Differentiating Characteristics:

Material controlled iaw ss800-ag-man-010/p-9290 system certification procedures and criteria manual for deep submergence systems and requires cleaning, packaging, and marking iaw mil-std-1622 or mil-std-1330 as deemed applicable. Critical items for safety and survival of deep submergence research and rescue vehicles as differentiated by special test features.

	Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fiig:

T299-g